





#### General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Gold
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	186 g/km
CO2 label	J





CV10HDU report date: 2024-03-28

&COLLECT

Internet history			
Entry 1			
Date	2021-09-18		
Pictures	4		
Listing price	View report		
	NEW ARRIVAL PHOTOS COMING SOON	We are HIGHLY RATED Customer reviewed on AutoTrader	CLICK

ALL ALL



source: autotrader.co.uk



# MOT history

MOT expiry date	2025-02-04
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	9
Total items failed	0

MOT #13	2024-01-12 08:59
MOT test number	907924802856
Result	✓ Passed
Next expiry date	2025-02-04

MOT #12	2023-01-09 09:31
MOT test number	883176566495
Result	✓ Passed

MOT #11	2022-01-19 10:56
MOT test number	458492851994
Result	✓ Passed

MOT #10	2021-01-21 15:13
MOT test number	908976249534
Result	✓ Passed

MOT #9		2021-01-21 11:40
MOT test	number	390090736553
Result		🗙 Failed
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	





MOT #8	2020-01-23 11:05	
MOT test number	303103239233	
Result	✓ Passed	
MOT #7	2019-02-05 09:34	
MOT test number	354626533283	
Result	✓ Passed	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MOT #6	2018-01-26 15:44	
MOT test number	256555917832	
Result	✓ Passed	

Advice Oil temp bypassed, no dipstick. emissions to low to get a reading

Advice Tyre worn close to the legal limit all four (4.1.E.1)

MOT #5	2017-01-20 14:33
MOT test number	148311610645
Result	✓ Passed
Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #4	2016-02-04 12:59
MOT test number	302850313513
Result	✓ Passed

MOT #3	2015-02-26 12:36
MOT test number	186547555006
Result	✓ Passed
Notice Emissions too low to read	
Advice Nearside Rear Tyre worn close	e to the legal limit (4.1.E.1)



CV10H	HDU
report date:	2024-03-28

MOT #2	2014-03-03 16:07
MOT test number	388862964033
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #1	2013-03-08 09:49
MOT test number	426527463081
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 September 2024	<b>Expires:</b> 4 February 2025
Tax status	Valid until 1 September
Days left	125
MOT expiry date	4 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE CO
Category	 Lashe
Туре	
Damage 2	AMPLE
Damaye 2	e e et al
Date	 1.
Category	 AMP
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.700
Auction value	4 10.000
Average private trade value	4 11 200





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-02
Last registration	2024-01-12
Complete history	See info



Registration #1	2010-03-02	12 mi
Registration #2	2013-03-08	48.056 mi
Registration #3	2014-03-03	61.913 mi
Registration #4	2015-02-26	77.376 mi
Registration #5	2016-02-04	92.909 mi
Registration #6	2017-01-20	108.278 mi
Registration #7	2018-01-26	122.934 mi
Registration #8	2019-02-05	137.865 mi
Registration #9		11.117 mi
Registration #10		11.117 esi
Registration #11		11.117 mi
Registration #12		11.117 est
Registration #13		11.117 esi
Registration #14		11.777 mi
Registration #15		11.117 esi





#### Car features

S0225	Air conditionin
\$0295	
50482	
S0501	
50566	
50567	
S0569	

# Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1879 kg
Max. allowed weight	2390 kg

### Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	795781