




report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA 16V EXCLUSIVE
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-09-28
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-29
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	27
Total items failed	7

## MOT #17 2023-08-30 13:11

MOT test number 326325715572

Result ✓ Passed

Next expiry date 2024-08-29

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Minor** Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

## MOT #16 2023-08-30 13:11

MOT test number 651131728811

Result ✗ Failed**Minor** Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Rear Stop lamp(s) not working both (4.3.1 (a) (ii))



<b>MOT #15</b>	2022-08-23 15:35
<b>MOT test number</b>	357207579346
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced outer sill (6.1.1 (c) (i))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread and rear (0.1 (b))

<b>MOT #14</b>	2022-08-23 15:35
<b>MOT test number</b>	580201651268
<b>Result</b>	✗ Failed
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread and rear (0.1 (b))
<b>Pass with rectification</b>	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Pass with rectification</b>	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced outer sill (6.1.1 (c) (i))

<b>MOT #13</b>	2021-03-10 14:12
<b>MOT test number</b>	391901775426
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Nearside Front Integral body structure is deformed but structural rigidity is not significantly reduced OUTER SILL (6.1.1 (a) (i))

**MOT #12** 2021-03-10 14:12**MOT test number** 729010589397**Result** ✗ Failed**Advice** Nearside Front Integral body structure is deformed but structural rigidity is not significantly reduced OUTER SILL (6.1.1 (a) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #11** 2020-03-12 16:39**MOT test number** 869297326011**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #10** 2019-03-13 14:57**MOT test number** 433389645955**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-03-12 13:28**MOT test number** 535412191690**Result** ✓ Passed**MOT #8** 2017-03-10 11:19**MOT test number** 348384095433**Result** ✓ Passed

**MOT #7** 2016-03-07 09:39**MOT test number** 599653197611**Result** ✓ Passed**Advice** Rear exhaust is corroded**MOT #6** 2016-03-07 09:39**MOT test number** 896954364299**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Rear exhaust is corroded**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2015-03-14 12:27**MOT test number** 276543475063**Result** ✓ Passed**MOT #4** 2014-03-07 10:43**MOT test number** 215056464087**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-02-28 12:11**MOT test number** 139699853492**Result** ✓ Passed**MOT #2** 2013-02-28 10:28**MOT test number** 646279653020**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)



MOT #1	2012-02-07 13:26
MOT test number	685658832061
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
29 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	29 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-02-13
Last registration	2023-08-30
Complete history	<a href="#">See info</a>



Registration #1	2009-02-13	29 mi
Registration #2	2012-02-07	31.246 mi
Registration #3	2013-02-28	36.605 mi
Registration #4	2013-02-28	36.605 mi
Registration #5	2014-03-07	39.852 mi
Registration #6	2015-03-14	43.990 mi
Registration #7	2016-03-07	48.137 mi
Registration #8	2016-03-07	48.137 mi
Registration #9	2017-03-10	53.864 mi
Registration #10	2018-03-12	61.046 mi
Registration #11	2019-03-20	65.277 mi
Registration #12	2019-03-20	65.277 mi
Registration #13	2019-03-20	65.277 mi
Registration #14	2019-03-20	65.277 mi
Registration #15	2019-03-20	65.277 mi
Registration #16	2019-03-20	65.277 mi
Registration #17	2019-03-20	65.277 mi
Registration #18	2019-03-20	65.277 mi
Registration #19	2019-03-20	65.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1667 mm
Height	1612 mm
Length	3860 mm
Wheel base	2460 mm
Kerb weight	1133 kg
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7S3417498