



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D4 SE AWD
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	21
Total items failed	6

MOT #13	2024-03-04 16:36
MOT test number	645904622916
Result	✓ Passed
Next expiry date	2025-03-29
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin both rear inner pads (1.1.13 (a) (ii))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	O/s/r exhaust heat shield slightly insecure
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre inner edge

**MOT #12**

2024-02-29 16:11

**MOT test number**

938541379126

**Result**

✗ Failed

**Fail** Front Headlamp aim too high both fronts (4.1.2 (a))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** O/s/r exhaust heat shield slightly insecure**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Rear Nail in tyre inner edge**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin both rear inner pads (1.1.13 (a) (ii))**MOT #11**

2023-03-04 09:34

**MOT test number**

489409575621

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on both inner and outer edge(s) (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on both inner and outer edge(s) (5.2.3 (e))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**Advice** Nearside Rear Nail in tyre On inner edge

**MOT #10** 2022-03-05 10:32**MOT test number** 183695618393**Result** ✓ Passed**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**MOT #9** 2021-03-30 15:51**MOT test number** 848507116406**Result** ✓ Passed**MOT #8** 2020-06-16 11:43**MOT test number** 636269075325**Result** ✓ Passed**MOT #7** 2020-06-16 11:43**MOT test number** 883446339808**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #6** 2019-06-24 11:12**MOT test number** 486999330713**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))**MOT #5** 2018-06-26 10:23**MOT test number** 516305908791**Result** ✓ Passed



MOT #4	2018-06-26 10:23
MOT test number	375993211769
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))

MOT #3	2017-06-26 15:53
MOT test number	675069191693
Result	✓ Passed

MOT #2	2016-05-19 09:50
MOT test number	174403067769
Result	✓ Passed

MOT #1	2015-06-04 11:00
MOT test number	856565655104
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
29 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	29 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-25
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2012-07-25	20 mi
Registration #2	2015-06-04	46.086 mi
Registration #3	2016-05-19	63.792 mi
Registration #4	2017-06-26	81.337 mi
Registration #5	2018-06-26	86.656 mi
Registration #6	2018-06-26	86.656 mi
Registration #7	2019-06-24	92.466 mi
Registration #8	2020-06-16	97.808 mi
Registration #9	2021-06-16	103.149 mi
Registration #10	2022-06-16	108.490 mi
Registration #11	2023-06-16	113.831 mi
Registration #12	2024-03-04	119.172 mi
Registration #13		
Registration #14		
Registration #15		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1840 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1162478