



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	White
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-08-14
Pictures	42
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-13
Pictures	42
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-12
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	27
Total items failed	2

MOT #14	2024-03-07 12:33
MOT test number	563066124043
Result	✓ Passed
Next expiry date	2025-03-12
Advice	Rear Exhaust mounting defective (6.1.2 (a))

MOT #13	2023-03-13 13:53
MOT test number	633088677547
Result	✓ Passed

MOT #12	2022-10-01 07:59
MOT test number	647709017773
Result	✓ Passed

MOT #11	2021-10-14 14:53
MOT test number	812490032153
Result	✓ Passed

**MOT #10**

2021-10-12 15:54

**MOT test number**

515354190661

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases centre to rear section slight blow (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- MAJOR** Nearside Front Steering linkage ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #9**

2021-02-15 16:49

**MOT test number**

629604636981

**Result****✓ Passed**

- Advice** Nearside front tyre at 2mm tread
- Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases leaking at rear tail box (6.1.2 (a))
- Advice** Both front tyres scrubbing on inner edges
- Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #8**

2021-02-15 15:20

**MOT test number**

119169465671

**Result****✗ Failed****Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases leaking at rear tail box (6.1.2 (a))**Advice** Both front tyres scrubbing on inner edges**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both rear (4.7.1 (b) (ii))**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside front tyre at 2mm tread**MOT #7**

2020-02-08 13:49

**MOT test number**

883814717973

**Result****✓ Passed****Advice** Nearside Front Track rod end slightly misaligned (2.1.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6**

2019-02-16 13:42

**MOT test number**

576450118971

**Result****✓ Passed**

**MOT #5** 2018-02-16 13:11**MOT test number** 361929588148**Result** ✓ Passed**Advice** Both front Tyres worn close to the legal limit and heavily perished**Advice** Offside rear outer brake disk facing slightly corroded**Advice** Both rear Tyres slightly perished**MOT #4** 2017-02-02 15:38**MOT test number** 898987946589**Result** ✓ Passed**MOT #3** 2017-02-01 11:10**MOT test number** 725443417623**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**MOT #2** 2016-02-18 16:02**MOT test number** 187265313996**Result** ✓ Passed**MOT #1** 2015-07-24 16:53**MOT test number** 526455905252**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
12 March 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	12 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>YR62LGE</b>
Plate since	2019-09-29
Current registration	 <b>YR62LGE</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-14
Last registration	2024-03-07
Complete history	<a href="#">See info</a>



Registration #1	2012-09-14	16 mi
Registration #2	2015-07-24	10.740 mi
Registration #3	2016-02-18	13.269 mi
Registration #4	2017-02-01	19.921 mi
Registration #5	2017-02-02	19.928 mi
Registration #6	2018-02-16	25.537 mi
Registration #7	2019-02-16	31.348 mi
Registration #8	2020-02-08	41.035 mi
Registration #9	2021-02-15	50.179 mi
Registration #10	2022-02-01	55.277 mi
Registration #11	2022-02-01	55.277 mi
Registration #12	2022-02-01	55.277 mi
Registration #13	2022-02-01	55.277 mi
Registration #14	2022-02-01	55.277 mi
Registration #15	2022-02-01	55.277 mi
Registration #16	2022-02-01	55.277 mi
Registration #17	2022-02-01	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1097033