



PEUGEOT

MW53MZZ


report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 SE
Colour	Grey
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	133 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	46.3 mpg





Internet history

Entry 1

Date	2021-09-10
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #19	2022-01-08 09:35
MOT test number	265796260607
Result	✓ Passed
Next expiry date	2023-01-17

MOT #18	2022-01-08 09:35
MOT test number	856139937665
Result	✗ Failed
Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	

MOT #17	2021-01-05 09:28
MOT test number	938717710759
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Central Exhaust mounting defective (6.1.2 (a))

MOT #16	2020-01-13 11:12
MOT test number	482603091690
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Central Exhaust mounting defective (6.1.2 (a))

MOT #15	2019-01-11 14:24
MOT test number	877908350908
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14** 2019-01-11 07:47**MOT test number** 207467466071**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2018-01-02 10:55**MOT test number** 654640667789**Result** ✓ Passed**MOT #12** 2018-01-02 08:15**MOT test number** 109458394003**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #11** 2017-01-05 14:36**MOT test number** 292860518777**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)

**MOT #10**

2017-01-05 08:48

MOT test number

732546137411

Result

✗ Failed

Fail Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Exhaust has a major leak of exhaust gases Joint between centre and rear sections (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)**MOT #9**

2016-01-18 15:06

MOT test number

867250492263

Result

✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8**

2016-01-16 11:31

MOT test number

173468901605

Result

✗ Failed

Advice Nearside Side repeater slightly discoloured (1.4.A.2f)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Oil leak**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Side repeater incorrect colour (1.4.A.2f)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2012-12-17 12:32**MOT test number** 747582752306**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #6** 2011-12-13 12:10**MOT test number** 985537141304**Result** ✓ Passed**MOT #5** 2010-12-09 12:45**MOT test number** 333573840330**Result** ✓ Passed**MOT #4** 2009-12-01 13:16**MOT test number** 870505839373**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Oil leak**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2008-12-10 11:24**MOT test number** 243505148349**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2007-11-23 11:20
MOT test number	833777027309
Result	✓ Passed
Notice	Both front tyres very close to limit

MOT #1	2006-12-08 10:14
MOT test number	192602446323
Result	✓ Passed
Notice	Nearside rear tyre grooved to outer sidewall
Notice	Front service brake disc pads look to be half worn



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-12-09
Last registration	2022-01-08
Complete history	See info



Registration #1	2003-12-09	17 mi
Registration #2	2006-12-08	14.400 mi
Registration #3	2007-11-23	22.808 mi
Registration #4	2008-12-10	29.572 mi
Registration #5	2009-12-01	36.958 mi
Registration #6	2010-12-09	44.142 mi
Registration #7	2011-12-13	49.858 mi
Registration #8	2012-12-17	57.102 mi
Registration #9	2016-01-16	57.277 mi
Registration #10	2016-01-18	57.277 mi
Registration #11	2017-01-05	60.611 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi
Registration #20	2019-05-20	55.277 mi
Registration #21	2019-05-20	55.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1049 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	FE010007386