





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO TSI
Colour	Silver
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	240 Nm at 1.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg



CarCheck.co.uk page 1/9



report date: 2024-03-29

MOT history

MOT #10	2020-03-11 17:00	
MOT test number	907662306524	
Result	✓ Passed	
Next expiry date	2021-03-12	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i))	ng in excessive movement	

MOT #9	2019-03-07 10:53
MOT test number	458984331696
Result	✓ Passed
MOT #8	2018-03-13 12:52
MOT test number	612752608395
Result	✓ Passed
MOT #7	2018-03-13 12:52
MOT test number	292387880863
Result	× Failed
Pass with rectification Offside Stop lamp not working (1.2.1b)	

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
MOT #6	2017-02-27 10:36
MOT test number	344129592816
Result	✓ Passed
MOT #5	2016-10-24 09:51
MOT test number	101585152288
Result	✓ Passed

CarCheck.co.uk page 2/9



report date: 2024-03-29

MOT #4		2015-10-20 16:11
MOT test	number	251338134361
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)		
MOT #3	2014-10-20 09:48	
MOT test number	929923094289	
Result	✓ Passed	
MOT #2	2013-10-21 15:38	
MOT test number	178824293255	
Result	✓ Passed	
MOT #1	2012-10-24 11:42	
MOT test number	368798492231	
Result	✓ Passed	
Notice Nail in nearside front tyre		

CarCheck.co.uk page 3/9



LS59VGR report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 4/9



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 5/9



LS59VGR report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many of VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow	



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 7/9



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-11-07
Last registration	2020-03-11
Complete history	See info



Registration #1	2009-11-07	12 mi
Registration #2	2012-10-24	15.442 mi
Registration #3	2013-10-21	21.137 mi
Registration #4	2014-10-20	26.326 mi
Registration #5	2015-10-20	30.170 mi
Registration #6	2016-10-24	33.823 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71,777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 8/9



LS59VGR report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
CarChaeleeaule	naga 0.10

CarCheck.co.uk page 9/9

Number of seats	4
Number of axles	2
Engine number	CAV 101705