






report date: 2024-03-28

### General information

Make	FIAT
Model	124 SPIDER MULTIAIR CLASSICA
Colour	Cream
Year of manufacture	1981
Top speed	134 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	240 Nm at 2.250 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-28

### Internet history

#### Entry 3

Date 2021-12-30

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-10-25
------	------------

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-10-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-04-25
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	10
Total items failed	42

MOT #12	2024-04-25 09:14
MOT test number	333741913370
Result	✓ Passed
Next expiry date	2025-04-25

MOT #11	2024-04-24 15:33
MOT test number	864965311702
Result	<b>X</b> Failed
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #10	2023-03-30 08:04
MOT test number	614365445497
Result	✓ Passed

MOT #9	2022-04-26 15:07
MOT test number	693422271516
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #8	2022-04-26 12:42
MOT test number	876896559775
Result	<b>×</b> Failed
Fail Rear fog lamp not working (4.5.1 (a) (ii))	

Rear fog lamp not working (4.5.1 (a) (ii))	
MOT #7	2021-07-16 09:43
MOT test number	151645387888
Result	<b>√</b> Passed
MOT #6	2020-02-18 11:39
MOT test number	834889439312
Result	<b>√</b> Passed
MOT #5	2019-01-21 09:03
MOT test number	219362118753
Result	✓ Passed
Minor Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))	
Minor Offside Front Position lamp incorrect colour (4.2.3 (a) (i))	

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #4 2019-01-16 10:25

**MOT test number** 625599457066

Result X Failed

**Fail** Nearside Inner Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Exhaust emissions hydrocarbon content excessive (8.2.1.2 (b))

Minor Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))

Fail Rear fog lamp missing (4.5.1 (a) (ii))

**Minor** Nearside Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Front Registration plate missing (0.1 (a))

Minor Offside Front Position lamp incorrect colour (4.2.3 (a) (i))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #3 2017-12-13 08:55

**MOT test number** 631435638162

**Result** ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #2 2017-12-05 13:43

MOT test number 848864282956

Result × Failed Fail Offside Headlamp aim beam image kick up to the offside (1.8) Fail Nearside front brake binding (3.7.B.1) Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b) Nearside rear brake recording little or no effort (3.7.B.5a) Fail Brake pedal anti-slip provision missing (3.3.A.1b) Fail **Advice** Movement in steering box components Fail Offside Inner Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c) Fail Direction indicators adversely affected by the operation of another lamp Not working with lights on (1.4.A.2h)Fail Nearside Headlamp aim beam image kick up to the offside (1.8) Fail Brake load sensing valve defective and function impaired (3.6.E.3) Fail Parking brake: efficiency below requirements (3.7.B.7) Fail Offside front brake binding (3.7.B.1) Fail Battery insecure (1.9.1) Fail Brakes imbalanced across an axle (3.7.B.5b) Offside rear brake recording little or no effort (3.7.B.5a) Fail Fail Direction indicators flashing less than 60 times a minute (1.4.A.2g) Fail Offside Outer Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c) Oil leak **Advice** 

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2017-08-02 10:23

**MOT test number** 869177321628

Result × Failed Fail Service brake: efficiency below requirements (3.7.B.7) Fail Rear Exhaust has a major leak of exhaust gases box fractured (7.1.2) Fail Nearside Headlamp aim beam image kick up to the offside (1.8) Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b) Fail **Advice** Ignition switch faulty Fail Offside front brake binding (3.7.B.1) Fail Nearside Obligatory mirror missing glass (8.1.1) Fail Rear parking (secondary) brakes imbalanced 39 % (3.7.B.6b) Fail Nearside Registration plate lamp not working (1.1.C.1d) **Advice** Oil leak gear oil Fail Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d) Fail Nearside Headlamp aim beam image kick up to the offside (1.8) Fail Parking brake: efficiency below requirements (3.7.B.7) Fail Nearside front brake binding (3.7.B.1) Offside Obligatory mirror missing (8.1.1) Fail **Advice** Gear box / engine mount fault? Fail Offside rear parking brake recording little or no effort (3.7.B.6a) Fail Offside Rear position lamp(s) not working (1.1.A.3b) Fail Offside Ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)Fail Offside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 7/14



report date: 2024-03-28

25 April 2025

See MOT history

#### Tax & MOT check

**MOT** expiry date

**Full MOT history** 



CarCheck.co.uk page 8/14



report date: 2024-03-28

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		e?
**************************************		
*************		
**************************************		
*************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	NK NE	
Plate since		
Current registration	UK CONTRACTOR	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	1981-01-01
Last registration	2024-04-25
Complete history	See info



Registration #1	1981-01-01	23 mi
Registration #2	2017-08-02	98.079 mi
Registration #3	2017-12-05	98.081 mi
Registration #4	2017-12-13	98.081 mi
Registration #5	2019-01-16	98.425 mi
Registration #6	2019-01-21	98.427 mi
Registration #7	2020-02-18	98.790 mi
Registration #8	2021-07-16	4.822 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		71.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Dimensions & weight

Width	1740 mm
Height	1233 mm
Length	4054 mm
Wheel base	2310 mm
Kerb weight	1050 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	NOT KNOWN

CarCheck.co.uk page 14/14