





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Blue
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-28


## Internet history


#### Entry 2

Date 2021-06-06

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-05-23

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

#### **MOT** history

**MOT #11** 2022-04-28 14:02

MOT test number 651871558448

**Result** ✓ Passed

Next expiry date 2023-04-27

**Advice** Central Exhaust mounting defective (6.1.2 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn smooth on outer edge and close to legal limit (5.2.3 (e))

**MOT #10** 2022-04-27 09:24

**MOT test number** 786629490199

Result X Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn smooth on outer edge and close to legal limit (5.2.3 (e))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Central Exhaust mounting defective (6.1.2 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9 2020-12-18 11:05

**MOT test number** 802048152679

**Result** ✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #8

MOT test number

950739689512

Result

Advice Stone chip in windscreen not affecting drivers view

MOT #7 2018-11-21 15:14 **MOT** test number 724544209450 Result Passed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6

MOT test number

Result

Advice Front Tyre worn close to the legal limit both sides on edges (4.1.E.1)

Advice Rear Tyre worn close to the legal limit both sides 3mm (4.1.E.1)

MOT #5

MOT test number

497694215496

Result

Advice Front brake discs some wear and pads low

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT test number
996244984250

Result
Advice Front brake discs worn

Advice Nearside Front Tyre worn close to the legal limit 3mm and worn on edge (4.1.E.1)

MOT test number

Result

Rear Exhaust system not adequately supported bracket corroded and broken (7.1.1)

Advice Front brake discs worn

Advice Nearside Front Tyre worn close to the legal limit 3mm and worn on edge (4.1.E.1)

MOT #2

MOT test number

238398944284

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Offside door mirror damaged

MOT test number

Fesult

Pass with rectification

Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Notice

Offside door mirror damaged

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



furthe scinors

PN61SYY

More info >

report date: 2024-03-28

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates

CarCheck.co.uk page 8/11



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-09-12
Last registration	2022-04-28
Complete history	See info



Registration #1	2011-09-12	14 mi
Registration #2	2014-09-05	27.866 mi
Registration #3	2015-09-04	37.320 mi
Registration #4	2015-09-04	37.320 mi
Registration #5	2016-09-07	44.812 mi
Registration #6	2017-09-12	50.538 mi
Registration #7	2018-11-21	56.759 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.074

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg

# Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

**Engine number** FSX46458693