



report date: 2024-03-28

General information

Make	MAZDA
Model	3 TS
Colour	Red
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-01
Pictures	0
Listing price	View report

source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-06
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	31
Total items failed	1

MOT #14	2024-04-05 11:28
MOT test number	427666084009
Result	✓ Passed
Next expiry date	2025-04-06

MOT #13	2023-04-07 14:22
MOT test number	254904994257
Result	✓ Passed

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened & all components corroded (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2023-03-30 10:33

MOT test number

434874158666

Result**✗ Failed****MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MAJOR** Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Rear Sub-frame corroded but not seriously weakened & all components corroded (5.3.3 (b) (i))**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner face badly corroded (1.1.14 (a) (ii))**MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #11**

2022-04-01 10:05

MOT test number

308621836896

Result**✓ Passed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Suspension component corroded but not seriously weakened all suspension components corroded (5.3.3 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #10** 2021-03-05 13:30**MOT test number** 162559422637**Result** ✓ Passed**MOT #9** 2020-12-04 14:51**MOT test number** 203482821396**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2019-06-05 15:50**MOT test number** 107359300622**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #7 2018-06-02 11:09**MOT test number** 137410516950**Result** ✓ Passed

- Advice** Both front tyres have slight wear on edges

MOT #6 2017-05-31 14:51**MOT test number** 194047500462**Result** ✓ Passed

**MOT #5** 2016-06-01 13:23**MOT test number** 240868730181**Result** ✓ Passed**MOT #4** 2015-04-16 12:15**MOT test number** 205766005434**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2014-03-12 12:18**MOT test number** 928871674044**Result** ✓ Passed**MOT #2** 2013-03-28 10:34**MOT test number** 656757583077**Result** ✓ Passed**MOT #1** 2013-03-27 11:08**MOT test number** 147176283043**Result** ✗ Failed**Fail** Nearside Rear Parking brake lever has no reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 April 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-31
Last registration	2024-04-05
Complete history	See info



Registration #1	2010-03-31	22 mi
Registration #2	2013-03-27	28.276 mi
Registration #3	2013-03-28	28.277 mi
Registration #4	2014-03-12	34.921 mi
Registration #5	2015-04-16	38.942 mi
Registration #6	2016-06-01	42.684 mi
Registration #7	2017-05-31	45.946 mi
Registration #8	2018-06-02	49.376 mi
Registration #9	2019-06-02	52.777 mi
Registration #10	2020-06-02	56.178 mi
Registration #11	2021-06-02	59.579 mi
Registration #12	2022-06-02	62.980 mi
Registration #13	2023-06-02	66.381 mi
Registration #14	2024-06-02	69.782 mi
Registration #15	2025-06-02	73.183 mi
Registration #16	2026-06-02	76.584 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4580 mm
Wheel base	2640 mm
Kerb weight	1235 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	Z6 862414