



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER S
Colour	Grey
Year of manufacture	2012
Top speed	134 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	46.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-08
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	5
Total items failed	3
MOT #12	2023-08-08 15:31
MOT test number	631587815695
Result	✓ Passed
Next expiry date	2024-08-12
MOT #11	2022-08-13 11:52
MOT test number	425486770548
Result	✓ Passed
MOT #10	2021-08-13 01:23
MOT test number	403710746169
Result	✓ Passed
MOT #9	2020-12-24 12:20
MOT test number	354971592524
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2020-12-24 11:24**MOT test number** 332191373750**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-07-03 16:26**MOT test number** 157375368735**Result** ✓ Passed**MOT #6** 2019-07-03 15:10**MOT test number** 853543168289**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))**MOT #5** 2018-06-11 10:45**MOT test number** 306987382112**Result** ✓ Passed**MOT #4** 2017-06-01 07:29**MOT test number** 687360011770**Result** ✓ Passed**Advice** Offside Rear tyre worn on inner edge**Advice** Nearside Front Nail in tyre**MOT #3** 2016-06-22 15:09**MOT test number** 395581549414**Result** ✓ Passed



MOT #2	2016-06-22 11:43
MOT test number	774978310363
Result	✗ Failed
<div><div>Fail</div>Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div>	

MOT #1	2015-05-07 12:29
MOT test number	517317725190
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
12 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	12 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	KE12OFD
Plate since	2019-09-29
Current registration	KE12OFD
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-05-24
Last registration	2023-08-08
Complete history	<a href="#">See info</a>



Registration #1	2012-05-24	20 mi
Registration #2	2015-05-07	15.336 mi
Registration #3	2016-06-22	25.410 mi
Registration #4	2016-06-22	25.410 mi
Registration #5	2017-06-01	31.560 mi
Registration #6	2018-06-11	37.476 mi
Registration #7	2019-07-03	44.583 mi
Registration #8	2020-05-20	51.277 mi
Registration #9	2020-05-20	51.277 mi
Registration #10	2020-05-20	51.277 mi
Registration #11	2020-05-20	51.277 mi
Registration #12	2020-05-20	51.277 mi
Registration #13	2020-05-20	51.277 mi
Registration #14	2020-05-20	51.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	B521J272