





report date: 2024-03-28

General information

Make	BMW
Model	318 318D LUXURY
Colour	Grey
Year of manufacture	2017
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2022-01-19

Pictures 6

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2022-01-15

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-20
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	23
Total items failed	6


MOT #7		2024-03-21 18:10
MOT test	number	615303601098
Result		✓ Passed
Next expiry date 2025-03-2		2025-03-20
Advice Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))		
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or co	ords (5.2.3 (d) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both	side (1.1.14 (a) (ii))

MOT #6	2024-03-21 13:58
MOT test number	451875186816
Result	X Failed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened	d both side (1.1.14 (a) (ii))
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply	y or cords (5.2.3 (d) (i))
Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	
Fail Electronic braking system warning device inoperative (1.7 (a))	
Advice Nearside Rear Parking brake efficiency only just met. It would apperequires adjustment or repair. (1.4.2 (a) (i))	ear that the braking system

CarCheck.co.uk page 3/12



report date: 2024-03-28



MOT #4	2022-10-19 09:	52
MOT test	number 9981873659	78
Result	✓ Pass	ed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDE (1.1.14 (a) (ii))	
Advice	Front Brake disc worn, but not excessively BOTH SIDE (1.1.14 (a) (i))	
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12



report date: 2024-03-28



MOT #2		2020-09-30 15:48
MOT test	number	982472167941
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #1	2020-09-30 14:55
MOT test number	508214170404
Result	× Failed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Front Windscreen washer not working both (3.5 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

^ -		histor	
- () ()	vnar	nictoi	٦.
\smile	VIICI	ппэсог	·v

,	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	

manuse .	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-28
Last registration	2024-03-21
Complete history	See info



Registration #1	2017-09-28	12 mi
Registration #2	2020-09-30	40.906 mi
Registration #3	2020-09-30	40.906 mi
Registration #4	2021-09-16	45.630 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1429 mm
Length	4633 mm
Wheel base	2810 mm
Kerb weight	1430 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2
Engine number 61619894