





report date: 2024-03-28

General information

Make	BMW
Model	525 530I M SPORT TOURING
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	320 Nm at 2.750 rpm
Engine capacity	2.996 сс
Cylinders	6
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	1



CarCheck.co.uk page 1/15



Internet history

Entry 2

Date 2021-07-05

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-13
Pictures	5

11000100

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-07-27
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	21
Total items failed	18

MOT #23		2023-07-13 14:59
MOT test r	number	119814064723
Result		✓ Passed
Next expir	y date	2024-07-27
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #2	22	2023-07-12 13:30
MOT te	st number	852345409154
Result		X Failed
Advic	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Nearside Rear Parking brake inoperative on one side 68 (1.4.1 (a))	
Fail obstruc	Driver's view of the road through the swept area of the windscreen significant $(3.1 (a) (ii))$	ly affected by an
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail	Offside Rear Parking brake inoperative on one side 15 (1.4.1 (a))	
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Advic	e Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/15



 MOT #21
 2022-07-28 15:37

 MOT test number
 228691489964

 Result
 ✓ Passed

 Advice
 Oil leak, but not excessive (8.4.1 (a) (i))

MOT test number

596658071546

Result

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #19

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/15



MOT #18 2021-03-17 11:43

MOT test number 473769774475

Result X Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Tyre has ply or cords exposed Split / Inner edge (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

MOT #17 2020-03-26 09:29

MOT test number 377270946740

Result ✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #16 2019-03-26 09:19

MOT test number 939604099544

Result ✓ Passed

MOT #15 2019-03-26 09:19

MOT test number 964426912243

Result X Failed

Pass with rectification Brake pedal has insufficient reserve travel (1.1.2 (a))

MOT #14 2018-03-22 18:08

MOT test number 194008192381

Result ✓ Passed

CarCheck.co.uk page 5/15



MOT #13 2018-03-22 13:35

MOT test number 738500343289

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #12 2017-12-19 11:09

MOT test number 249808818369

Result ✓ Passed

MOT #11 2017-01-04 12:34

MOT test number 642630602283

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2016-01-08 15:50

MOT test number 321034643057

Result

Passed

MOT #9 2016-01-06 10:34

MOT test number 269541615537

Result X Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/15



MOT #8	2015-01-06 11:20
MOT test number	758036105070
Result	✓ Passed
MOT #7	2014-04-18 16:42
MOT test number	308958404188
Result	✓ Passed
MOT #6	2013-04-11 10:41
MOT test number	879811403159
Result	✓ Passed
MOT #5	2012-04-26 17:27
MOT test number	108687912103
Result	✓ Passed
MOT #4	2012-04-26 15:16
MOT test number	969337012112
Result	★ Failed
Notice Tread wearing low on inner edge on o/s/r tyre	
Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)	

MOT #3	2011-08-23 10:14
MOT test number	248945131263
Result	✓ Passed

CarCheck.co.uk page 7/15



MOT #2 2011-08-19 08:31

MOT test number 465271831281

Result

× Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-08-10 08:29

MOT test number 343472720468

Result ✓ Passed

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	ENER AIX UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-05-11
Last registration	2023-07-13
Complete history	See info



Registration #1	2007-05-11	17 mi
Registration #2	2010-08-10	25.414 mi
Registration #3	2011-08-19	53.291 mi
Registration #4	2011-08-23	32.770 mi
Registration #5	2012-04-26	37.304 mi
Registration #6	2012-04-26	37.305 mi
Registration #7	2013-04-11	46.348 mi
Registration #8	2014-04-18	53.016 mi
Registration #9	2015-01-06	58.576 mi
Registration #10	2016-01-06	63.708 mi
Registration #11	2016-01-08	63.737 mi
Registration #12	2017-01-04	69.079 mi
Registration #13	2017-12-19	74.937 mi
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.772 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		0.07 44

CarCheck.co.uk page 14/15



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1491 mm
Length	4843 mm
Wheel base	2886 mm
Kerb weight	1630 kg
Max. allowed weight	2230 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

Engine number 76094034