



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC XMOD EXPRESSION PLUS VVT
Colour	Black
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-06-05
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	12
Total items failed	10

MOT #13	2023-06-06 14:27
MOT test number	338985213651
Result	✓ Passed
Next expiry date	2024-06-05

MOT #12	2023-06-05 09:06
MOT test number	370675653554
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11	2022-04-01 13:12
MOT test number	522132133114
Result	✓ Passed

**MOT #10** 2021-04-08 15:20**MOT test number** 935993624637**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge ** Tyre also cracked/perished ** (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2020-10-27 12:34**MOT test number** 129385638746**Result** ✓ Passed**MOT #8** 2020-10-27 09:20**MOT test number** 540158705322**Result** ✗ Failed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Offside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #7 2020-05-29 09:01**MOT test number** 459486999595**Result** ✓ Passed**MOT #6** 2019-07-22 16:03**MOT test number** 420823297742**Result** ✓ Passed

**MOT #5** 2019-07-22 07:44**MOT test number** 527500930559**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2018-08-07 07:52**MOT test number** 386608024089**Result** ✓ Passed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #3** 2017-08-09 08:25**MOT test number** 692344517573**Result** ✓ Passed**MOT #2** 2017-08-09 08:25**MOT test number** 106334064346**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #1	2016-09-01 12:15
MOT test number	904095614921
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
5 June 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-10
Last registration	2023-06-06
Complete history	See info



Registration #1	2013-09-10	18 mi
Registration #2	2016-09-01	46.448 mi
Registration #3	2017-08-09	64.364 mi
Registration #4	2017-08-09	64.364 mi
Registration #5	2018-08-07	79.229 mi
Registration #6	2019-07-22	94.050 mi
Registration #7	2019-07-22	94.051 mi
Registration #8	2020-05-29	104.450 mi
Registration #9	2020-05-29	104.450 mi
Registration #10	2020-05-29	104.450 mi
Registration #11	2020-05-29	104.450 mi
Registration #12	2020-05-29	104.450 mi
Registration #13	2020-05-29	104.450 mi
Registration #14	2020-05-29	104.450 mi
Registration #15	2020-05-29	104.450 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1845 mm
Height	1656 mm
Length	4372 mm
Wheel base	2704 mm
Kerb weight	1400 kg
Max. allowed weight	1936 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D132821