



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SPORT
Colour	Grey
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 2


Date	2021-10-16
Pictures	24
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-10-02
Pictures	24
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-01
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	30
Total items failed	4

MOT #20	2023-09-27 13:10
MOT test number	169261824984
Result	✓ Passed
Next expiry date	2024-10-01

MOT #19	2022-09-21 13:20
MOT test number	859570185679
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2021-10-02 11:34
MOT test number	428232138681
Result	✓ Passed

MOT #17	2021-09-29 10:51
MOT test number	460575111316
Result	✗ Failed
MAJOR	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Clip missing (6.1.7 (g) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #16	2020-09-25 15:31
MOT test number	903253109260
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

MOT #15	2020-09-25 12:06
MOT test number	501474154779
Result	✗ Failed
MAJOR	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
MAJOR	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

MOT #14	2019-09-20 14:09
MOT test number	709393945883
Result	✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13	2019-09-20 11:27
MOT test number	913666516359
Result	✗ Failed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))



MOT #12	2018-09-14 15:47
MOT test number	832992014534
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2018-09-14 12:49
MOT test number	133639149140
Result	✗ Failed
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front inner (1.1.14 (a) (ii))
MAJOR	Offside Front Side repeater light intensity significantly reduced (4.4.3 (a))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2017-09-20 13:29
MOT test number	594785475345
Result	✓ Passed
Advice	Front Inner brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)

MOT #9	2017-09-20 10:45
MOT test number	949942487907
Result	✗ Failed
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Front Inner brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)
Fail	Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #8** 2016-09-23 10:55**MOT test number** 484559699007**Result** ✓ Passed**Advice** Advise front brakes caliper pistons allmost fully extended plus front brake discs faces not true .**MOT #7** 2016-09-22 14:38**MOT test number** 394033457752**Result** ✗ Failed**Advice** Advise front brakes caliper pistons allmost fully extended plus front brake discs faces not true .**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2015-08-21 12:00**MOT test number** 158098378986**Result** ✓ Passed**MOT #5** 2015-08-21 09:46**MOT test number** 359480177446**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2014-04-01 13:30**MOT test number** 275931794090**Result** ✓ Passed

**MOT #3** 2013-04-18 14:58**MOT test number** 869948103145**Result** ✓ Passed**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-04-04 09:49**MOT test number** 287155692074**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2011-04-28 09:46**MOT test number** 805028711147**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
1 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-07-17
Last registration	2023-09-27
Complete history	See info



Registration #1	2008-07-17	24 mi
Registration #2	2011-04-28	29.170 mi
Registration #3	2012-04-04	36.668 mi
Registration #4	2013-04-18	49.654 mi
Registration #5	2014-04-01	56.084 mi
Registration #6	2015-08-21	72.261 mi
Registration #7	2015-08-21	72.261 mi
Registration #8	2016-09-22	82.026 mi
Registration #9	2016-09-23	82.029 mi
Registration #10	2017-09-20	90.050 mi
Registration #11	2017-09-20	90.050 mi
Registration #12	2018-09-14	96.091 mi
Registration #13	2019-09-14	102.132 mi
Registration #14	2019-09-14	102.132 mi
Registration #15	2020-09-14	108.173 mi
Registration #16	2020-09-14	108.173 mi
Registration #17	2021-09-14	114.214 mi
Registration #18	2021-09-14	114.214 mi
Registration #19	2022-09-14	120.255 mi
Registration #20	2022-09-14	120.255 mi
Registration #21	2023-09-14	126.296 mi
Registration #22	2023-09-14	126.296 mi
Registration #23	2023-09-27	132.337 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1738 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 282994