





General information

Make	AUDI
Model	A4 TDI S LINE DPF
Colour	Red
Year of manufacture	2009
Top speed	131 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	Н





MOT history

MOT expiry date	2024-06-30
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	17
Total items failed	18

MOT #19	2023-07-01 07:54
MOT test number	577605854067
Result	✓ Passed
Next expiry date	2024-06-30

MOT #18	2022-05-27 11:00
MOT test number	882639643223
Result	✓ Passed

MOT #3	17 2	022-05-27 09:18
MOT te	st number	489713221661
Result		🗙 Failed
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b)	(ii))

MOT #16	2020-11-18 13:01
MOT test number	994445722000
Result	✓ Passed





MOT #15	2020-11-16 16:21	
MOT test number	873928218093	
Result	🗙 Failed	
FailOffside Rear Registration plate lamp inoperative in the case of a single lamp or all(ii))	l lamps (4.7.1 (b)	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Central exhaust heat shield insecure		
Fail Rear fog lamp not working (4.5.1 (a) (ii))		
Advice Rear exhaust heat shield insecure		
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach t (5.2.3 (d) (i))	he ply or cords	

MOT #14	2019-12-27 15:07
MOT test number	315867017619
Result	✓ Passed

MOT #13	2019-01-11 14:49
MOT test number	539287673299
Result	✓ Passed

MOT #12	2018-01-08 13:43
MOT test number	191681363163
Result	✓ Passed
Advice Advise front disks zone b chiped	

MOT #11	2017-01-12 14:34
MOT test number	105011678755
Result	✓ Passed





MOT #10	2016-09-24 07:52
MOT test number	781328240627
Result	✓ Passed
МОТ #9	2015-09-30 15:21
MOT test number	697971341834
Result	✓ Passed

MOT #	*8	2015-09-30 08:31
MOT t	est number	924024700543
Result		🗙 Failed
Fail	Nearside Rear position lamp(s) not working (1.1.A.3b)	
Fail	Offside Registration plate lamp not working (1.1.C.1d)	
Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)		ure (4.1.D.1b)

MOT #7		2014-09-25 17:15
MOT test	number	807918864225
Result		🗸 Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice Under-trays fitted obscuring some underside components		

MOT #6		2014-05-02 11:38
MOT test	number	626062324199
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		3.1d)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	



PK09DPY
report date: 2024-03-28

MOT #5	2014-04-28 16:48
MOT test number	856108214155
Result	🗙 Failed
Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Rear registration plate character(s) incorrectly spaced (6.3.4a)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8	.3.1d)
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach (4.1.D.1a)	the ply or cords
Fail Front registration plate character(s) incorrectly spaced (6.3.4a)	
Fail Exhaust emits excessive smoke or vapour of any colour (7.4.B.4)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #4		2013-05-01 15:56
MOT test I	number	506771623142
Result		✓ Passed
Advice	Front Windscreen has damage to an area less than a 40mm circle outside	zone 'A' (8.3.1d)

MOT #3	2013-05-01 11:24	
MOT test number	269911423416	
Result	🗙 Failed	
Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
FailOffside Front Tyre has ply or cords exposed (4.1.D.1b)		



PK09DPY
report date: 2024-03-28

MOT #2	2012-04-26 17:07
MOT test number	735647212168
Result	✓ Passed
Notice Rear inner pads starting to get low	
Notice Chip in top n/s of windscreen(not over 40mm)	
MOT #1	2012-04-25 15:54
MOT test number	517836212199
Result	× Failed
Fail Rear registration plate character(s) incorrectly spaced (6.3.4a)	
Notice Rear inner pads starting to get low	
Fail Front registration plate character(s) incorrectly spaced (6.3.4a)	
Notice Chip in top n/s of windscreen(not over 40mm)	



Tax & MOT check

✓ Taxed	√ МОТ
Tax due: 1 July 2024	Expires: 30 June 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Rinda since	
Plane anna	





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



PK09DPY report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-28
Last registration	2023-07-01
Complete history	<u>See info</u>



Registration #2 2012-04-25 39.810 mi Registration #3 2012-04-26 39.902 mi Registration #4 2013-05-01 67.100 mi Registration #5 2013-05-01 67.100 mi Registration #6 2014-04-28 87.911 mi Registration #7 2014-05-02 88.024 mi Registration #8 2014-09-25 89.210 mi Registration #9 2015-09-30 98.871 mi			
Registration #3 2012-04-26 39.902 mi Registration #4 2013-05-01 67.100 mi Registration #5 2013-05-01 67.100 mi Registration #5 2014-04-28 87.911 mi Registration #6 2014-04-28 87.911 mi Registration #7 2014-05-02 88.024 mi Registration #8 2014-09-25 89.210 mi Registration #9 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #11 Image: Comparison of the second of th	Registration #1	2009-03-28	29 mi
Registration #4 2013-05-01 67.100 mi Registration #5 2013-05-01 67.100 mi Registration #6 2014-04-28 87.911 mi Registration #7 2014-05-02 88.024 mi Registration #8 2014-09-25 89.210 mi Registration #9 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #15 T T Registration #16 T T Registration #18 T T Registration #19 T T	Registration #2	2012-04-25	39.810 mi
Registration #5 2013-05-01 67.100 mi Registration #6 2014-04-28 87.911 mi Registration #7 2014-05-02 88.024 mi Registration #8 2014-09-25 89.210 mi Registration #9 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #16 T T Registration #18 T T Registration #18 T T	Registration #3	2012-04-26	39.902 mi
Registration #6 2014-04-28 87.911 mi Registration #7 2014-05-02 88.024 mi Registration #8 2014-09-25 89.210 mi Registration #9 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #11	Registration #4	2013-05-01	67.100 mi
Registration #7 2014-05-02 88.024 mi Registration #8 2014-09-25 89.210 mi Registration #9 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #11 Image: Comparison of the state of t	Registration #5	2013-05-01	67.100 mi
Registration #8 2014-09-25 89.210 mi Registration #9 2015-09-30 98.871 mi Registration #10 2015-09-30 98.871 mi Registration #11 2015-09-30 98.871 mi Registration #11 2015-09-30 98.871 mi Registration #11 2015-09-30 98.871 mi Registration #12 2015-09-30 98.871 mi Registration #13 2015-09-30 98.871 mi Registration #13 2015-09-30 98.871 mi Registration #13 2015-09-30 98.871 mi Registration #14 2015-09-30 98.871 mi Registration #14 2015-09-30 98.871 mi Registration #15 2015-09-30 98.871 mi Registration #16 2015-09-30 98.871 mi Registration #18 2015-09-30 98.871 mi Registration #19 2015-09-30 98.871 mi	Registration #6	2014-04-28	87.911 mi
Registration #92015-09-3098.871 miRegistration #102015-09-3098.871 miRegistration #112015-09-3098.871 miRegistration #112015-09-3098.871 miRegistration #122015-09-3098.871 miRegistration #132015-09-3098.871 miRegistration #142015-09-3098.871 miRegistration #152015-09-3098.871 miRegistration #162015-09-3098.871 miRegistration #172015-09-3098.871 miRegistration #182015-09-3098.871 miRegistration #192015-09-3098.871 mi	Registration #7	2014-05-02	88.024 mi
Registration #102015-09-3098.871 miRegistration #11Registration #12Registration #13Registration #13Registration #14Registration #14Registration #15Registration #15Registration #16Registration #16Registration #17Registration #18Registration #18Registration #19Registration #19	Registration #8	2014-09-25	89.210 mi
Registration #11Registration #12Registration #13Registration #14Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19	Registration #9	2015-09-30	98.871 mi
Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19	Registration #10	2015-09-30	98.871 mi
Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19	Registration #11		11.707 est
Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19	Registration #12		11.777 est
Registration #15Registration #16Registration #17Registration #18Registration #19	Registration #13		11.707 est
Registration #16 Registration #17 Registration #18 Registration #19	Registration #14		11.777 est
Registration #17 Registration #18 Registration #19	Registration #15		11.707 est
Registration #18 Registration #19	Registration #16		11.777 est
Registration #19	Registration #17		11.707 est
	Registration #18		11.777 est
Registration #20	Registration #19		11.777 est
	Registration #20		11.117 est







Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

NCAP rating

Engine number CarCheck.co.uk

Video

see crash video



Dimensions & weight	
Width	1777 mm
Height	1391 mm
Length	4573 mm
Wheel base	2650 mm
Max. allowed weight	2080 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2

BPW 133960