





report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Blue
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	1



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-03-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	31
Total items failed	2

MOT #16		2024-02-05 09:18
MOT test	number	665136870095
Result		✓ Passed
Next expi	ry date	2025-02-17
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15		2023-02-10 11:20
MOT test	number	801375019592
Result		✓ Passed
Advice	Nearside Rear Oil leak, but not excessive Diff Leak (8.4.1 (a) (i))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #14		2023-02-08 11:43
MOT test	number	833882507967
Result		× Failed
Advice	Nearside Rear Oil leak, but not excessive Diff Leak (8.4.1 (a) (i))	
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #12 2022-02-12 17:09 **MOT** test number 414285229438 Result × Failed **DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11

MOT test number

611125441258

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

MOT test number

120007272292

Result

Advice Emission too clean to record

CarCheck.co.uk page 4/13



Result

KP60TUH

report date: 2024-03-29

✓ Passed

MOT #9

MOT test number

529173191071

Result

Advice Front brake discs worn

Advice Rear brake discs corroded

MOT #8 2019-05-16 14:19 **MOT** test number 899439217844 Result **X** Failed **DANGEROUS** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Exhaust particulate filter obviously defective Dpf light flashing (8.2.2.1 (a)) **MAJOR** Advice Rear brake discs corroded **DANGEROUS** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **MAJOR** Exhaust has a major leak of exhaust gases Rear silencer detached from vehicle (6.1.2 (a)) **Advice** Front brake discs worn

MOT #7	2018-05-20 13:19
MOT test number	369440513003
Result	✓ Passed
MOT #6	2017-05-22 15:48
MOT test number	412384824442

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #5

MOT test number

516829053544

Result

Advice Ad blue/dpf lamp on dash

Advice Rear wiper rubber split/worn

MOT test number 966180074450

Result X Failed

Pass with rectification (8.2.2)

Advice Rear wiper rubber split/worn

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Ad blue/dpf lamp on dash

 MOT #3
 2015-07-25 15:51

 MOT test number
 369166705427

 Result
 ✓ Passed

MOT #2

MOT test number

Result

Notice N/s/f and o/s/f inner faces of brake discs pitted/corroded

2014-11-07 12:28

467501014433

✔ Passed

 MOT #1
 2013-11-29 14:08

 MOT test number
 937393133339

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Venicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

KP60TUH

report date: 2024-03-29

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

See in this check if this MAZDA had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-11-30
Last registration	2024-02-05
Complete history	See info



Registration #1	2010-11-30	20 mi
Registration #2	2013-11-29	32.203 mi
Registration #3	2014-11-07	41.734 mi
Registration #4	2015-07-25	45.663 mi
Registration #5	2016-07-13	49.969 mi
Registration #6	2016-07-13	49.969 mi
Registration #7	2017-05-22	54.583 mi
Registration #8	2018-05-20	59.909 mi
Registration #9	2019-05-16	68.463 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		91,700 esi
Registration #18		71.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	***
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Kerb weight	1865 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10267131

CarCheck.co.uk page 13/13