



report date: 2024-03-28

General information

Make	MAZDA
Model	6 D SPORT NAV
Colour	Red
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.200 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-12-10
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-09
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-02-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #8 2024-02-05 12:33

MOT test number 785778645119

Result ✓ Passed

Next expiry date 2025-02-04

- Advice** Rear exhaust heat shield insecure
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2022-09-23 14:41

MOT test number 271661949843

Result ✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm back bush (5.3.4 (a) (i))
- Advice** Nsr brake pads wearing low
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm back bush (5.3.4 (a) (i))

**MOT #6**

2022-09-23 11:53

MOT test number

734941705352

Result**✗ Failed**

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure body cords exposed (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm back bush (5.3.4 (a) (i))

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure body cords exposed (5.2.3 (d) (ii))

Advice Nsr brake pads wearing low

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm back bush (5.3.4 (a) (i))

MOT #5

2021-07-26 15:15

MOT test number

195477640414

Result**✓ Passed****MOT #4**

2020-09-18 09:43

MOT test number

947805104493

Result**✓ Passed**

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge wearing on inner edge badly (5.2.3 (e))

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened poor (1.1.14 (a) (ii))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

MOT #3

2020-09-18 09:20

MOT test number

418522191218

Result**✗ Failed**

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge wearing on inner edge badly (5.2.3 (e))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened poor (1.1.14 (a) (ii))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))



MOT #2	2019-09-17 09:00
MOT test number	449121251780
Result	✓ Passed

MOT #1	2018-09-17 08:44
MOT test number	309788747414
Result	✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
4 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YH65XGA
Plate since	2019-09-28
Current registration	YH65XGA
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-29
Last registration	2024-02-05
Complete history	See info



Registration #1	2015-09-29	23 mi
Registration #2	2018-09-17	49.645 mi
Registration #3	2019-09-17	64.930 mi
Registration #4	2020-09-18	75.607 mi
Registration #5	2020-09-18	75.607 mi
Registration #6	2020-09-18	75.607 mi
Registration #7	2020-09-18	75.607 mi
Registration #8	2020-09-18	75.607 mi
Registration #9	2020-09-18	75.607 mi
Registration #10	2020-09-18	75.607 mi
Registration #11	2020-09-18	75.607 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2750 mm
Kerb weight	1420 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	SH 30560143