



report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD 16V
Colour	Black
Year of manufacture	2000
Top speed	150 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	236 BHP
Max. torque	204 Nm at 7.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	28.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2024-06-29
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	29
Total items failed	24

MOT #27	2023-06-30 10:24
MOT test number	844157288645
Result	✓ Passed
Next expiry date	2024-06-29

MOT #26	2023-06-14 15:56
MOT test number	730758576080
Result	✗ Failed
Fail	Offside Front Windscreen washer not working (3.5 (a))
Fail	Nearside Front Headlamp lens seriously defective Discoloured (4.1.1 (b) (ii))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Front Windscreen washer not working (3.5 (a))
Fail	Offside Front Headlamp lens seriously defective Discoloured (4.1.1 (b) (ii))
Fail	Nearside Rear Direction indicator not working (4.4.1 (a) (ii))

MOT #25	2022-05-13 13:47
MOT test number	257635651279
Result	✓ Passed

**MOT #24** 2021-04-08 12:37**MOT test number** 958293214186**Result** ✓ Passed**MOT #23** 2020-08-06 08:45**MOT test number** 203548409773**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 due to being stood (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #22** 2020-08-05 08:10**MOT test number** 126155907110**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 due to being stood (1.1.14 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #21**

2019-08-15 14:49

MOT test number

354863946824

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #20**

2018-08-08 10:23

MOT test number

218733790815

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19**

2017-08-09 11:18

MOT test number

820761275253

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #18**

2016-08-09 14:00

MOT test number

285169837265

Result

✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #17** 2016-08-09 14:00**MOT test number** 772541717168**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #16** 2015-08-06 11:03**MOT test number** 918134785996**Result** ✓ Passed**MOT #15** 2015-08-04 15:00**MOT test number** 688796315283**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** All four tyres perished and cracking on side walls**Fail** Nearside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #14** 2014-08-12 10:26**MOT test number** 318154624246**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** All 4 tyres perished on side walls

**MOT #13** 2014-08-11 12:15**MOT test number** 635593924237**Result** ✗ Failed**Notice** All 4 tyres perished on side walls**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2013-08-05 14:57**MOT test number** 897047913273**Result** ✓ Passed**MOT #11** 2013-07-29 12:27**MOT test number** 315070813206**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage insecure (2.4.G.1)**MOT #10** 2012-08-02 14:47**MOT test number** 466265412206**Result** ✓ Passed**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Notice** Exhaust joint middle/back corroded

**MOT #9** 2012-08-02 14:47**MOT test number** 759195912259**Result** ✗ Failed**Notice** Exhaust joint middle/back corroded**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2011-08-15 16:55**MOT test number** 196697021223**Result** ✓ Passed**MOT #7** 2011-08-08 13:57**MOT test number** 516370821287**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #6** 2010-08-04 13:41**MOT test number** 262636910256**Result** ✓ Passed**MOT #5** 2009-08-18 08:39**MOT test number** 474540239293**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #4** 2008-07-07 16:24**MOT test number** 401239888119**Result** ✓ Passed



MOT #3	2008-07-01 12:42
MOT test number	162723688164
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2	2007-06-28 10:59
MOT test number	612749577136
Result	✓ Passed

MOT #1	2006-07-05 11:07
MOT test number	854366086178
Result	✓ Passed



Tax & MOT check

✗
Untaxed

Tax expired:
1 June 2023

✓
MOT

Expires:
29 June 2024

Tax status	Expired at 1 June 2023
Days left	334 days too late
MOT expiry date	29 June 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	W257TLK
Plate since	2019-03-28
Current registration	W257TLK
Plate since	2019-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2000-07-10
Last registration	2023-06-30
Complete history	See info



Registration #1	2000-07-10	22 mi
Registration #2	2006-07-05	24.133 mi
Registration #3	2007-06-28	26.490 mi
Registration #4	2008-07-01	28.225 mi
Registration #5	2008-07-07	28.231 mi
Registration #6	2009-08-18	30.731 mi
Registration #7	2010-08-04	33.013 mi
Registration #8	2011-08-08	35.395 mi
Registration #9	2011-08-15	35.460 mi
Registration #10	2012-08-02	39.337 mi
Registration #11	2013-07-29	43.149 mi
Registration #12	2013-08-05	43.220 mi
Registration #13	2014-08-11	45.915 mi
Registration #14	2014-08-12	45.915 mi
Registration #15	2015-08-02	48.227 mi
Registration #16	2015-08-02	48.227 mi
Registration #17	2015-08-02	48.227 mi
Registration #18	2015-08-02	48.227 mi
Registration #19	2015-08-02	48.227 mi
Registration #20	2015-08-02	48.227 mi
Registration #21	2015-08-02	48.227 mi
Registration #22	2015-08-02	48.227 mi
Registration #23	2015-08-02	48.227 mi
Registration #24	2015-08-02	48.227 mi
Registration #25	2015-08-02	48.227 mi
Registration #26	2015-08-02	48.227 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1285 mm
Length	4135 mm
Kerb weight	1271 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	F20C21002819