





report date: 2024-03-29

General information

| Make | FORD |
|---------------------|---------------------|
| Model | S-MAX TITANIUM TDCI |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 124 mph |
| 0 - 60 mph | 10.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 161 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-12-03

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT #11 2022-12-28 17:00

MOT test number 486996805148

Result ✓ Passed

Next expiry date 2023-12-27

MOT #10 2022-12-14 12:48

MOT test number 158737137264

Result X Failed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9 2021-12-14 10:02

MOT test number 566883586894

Result ✓ Passed

MOT #8 2020-09-22 11:28

MOT test number 868798212261

Result \(\sqrt{Passed} \)

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Coil spring corroded both rear springs (5.3.1 (b) (i))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #7 2019-09-18 13:13

MOT test number 956851502353

CarCheck.co.uk page 3/11



MOT #6 2019-09-16 15:16

MOT test number 538767909248

Result X Failed

Fail Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Fail Reversing lamp inoperative (4.6.1 (a))

Fail Nearside Rear Suspension arm pin or bush excessively worn Trailing Arm Bush (5.3.4 (a) (i))

MOT #5 2018-09-17 09:08

MOT test number 790587491390

Result ✓ Passed

Advice Nearside Rear Trailing arm bush slight deterioration, no excessive movement

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Foglamp push back inside bumper

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2017-09-04 13:35

MOT test number 674361448591

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement starting to seperate (2.4.G.2)

Advice Front tyres slight wear on inner edges

CarCheck.co.uk page 4/11



MOT #3 2016-09-15 11:18

MOT test number 324224201033

Result ✓ Passed

Advice Rear Tyre worn close to the legal limit NS and OS (4.1.E.1)

Advice NS wing mirror housing damaged

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Passenger seat(s) missing at time of test Rear extra seats

MOT #2 2016-09-15 11:18

MOT test number 456359199522

Result X Failed

Advice Passenger seat(s) missing at time of test Rear extra seats

Pass with rectification Centre Stop lamp not working (1.2.1b)

Advice Rear Tyre worn close to the legal limit NS and OS (4.1.E.1)

Advice NS wing mirror housing damaged

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2015-09-24 09:50

MOT test number 633854983760

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice NSR tyre outer sidewall damaged

Advice Front Tyre worn close to the legal limit NS and OS (4.1.E.1)

Advice Engine covers and under trays fitted

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



| Owner history | _ | | | |
|---------------|------|-----|--------|-------|
| | O | 205 | bicte | - m / |
| | UVVI | 161 | 111510 |)IV |

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report | |
|--|-------------|
| | |
| | |
| | |
| | |
| PROPERTY. | |
| *************************************** | |
| ************ | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | |
| Current registration | AIR. |
| Plate since | |
| Current registration | NK SIN |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2012-09-17 |
| Last registration | 2022-12-28 |
| Complete history | See info |



| Registration #1 | 2012-09-17 | 20 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-09-24 | 39.365 mi |
| Registration #3 | 2016-09-15 | 52.815 mi |
| Registration #4 | 2016-09-15 | 52.815 mi |
| Registration #5 | 2017-09-04 | 68.030 mi |
| Registration #6 | 2018-09-17 | 82.436 mi |
| Registration #7 | 2019-09-16 | 94.950 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 10.377 au |

More info >

CarCheck.co.uk page 10/11



Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1884 mm |
|---------------------|---------|
| Height | 1764 mm |
| Length | 4820 mm |
| Wheel base | 2850 mm |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 70 |
|---------------------------------|--------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number CarCheck.co.uk | BS48457 page 11/11 |