





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY DSG
Colour	Black
Year of manufacture	2012
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-01-24

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-27
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	8
Total items failed	8

MOT #13		2024-02-28 15:13
MOT test	number	357908862664
Result		✓ Passed
Next expiry date 2025-02-		2025-02-27
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2024-02-23 13:42
MOT test number	624902842991
Result	× Failed
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2023-12-21 18:29
MOT test number	928538267714
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

YY12JUX report date: 2024-03-28

Passed

MOT #10

MOT test number

628870888351

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #9
 2022-01-26 14:26

 MOT test number
 424605419685

 Result
 ✓ Passed

 MOT #8
 2021-02-01 16:05

 MOT test number
 416301690963

MOT #7

MOT test number

Result

Fail Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #6 2021-01-08 14:27 **MOT** test number 707902089862 Result × Failed Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Nearside Front Macpherson strut top bush or bearing has excessive wear or free play bearing collapsed. (5.3.4 (a) (i)) Fail Service brake efficiency below requirements (1.2.2 (a) (i)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Nearside Front Brake disc significantly and obviously worn inner face (1.1.14 (a) (i))

CarCheck.co.uk page 4/12



MOT test number

Result

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #4	2018-04-27 12:10
MOT test number	500814974657
Result	✓ Passed
MOT #3	2017-04-11 08:46
MOT test number	571660897195
Result	✓ Passed
MOT #2	2016-04-20 14:50
MOT test number	311055142013
Result	✓ Passed
MOT #1	2015-05-27 14:40
MOT test number	547427845189
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-31
Last registration	2024-02-28
Complete history	See info



Registration #1	2012-05-31	9 mi
Registration #2	2015-05-27	28.128 mi
Registration #3	2016-04-20	35.655 mi
Registration #4	2017-04-11	42.951 mi
Registration #5	2018-04-27	50.933 mi
Registration #6	2019-06-04	55.543 mi
Registration #7	2021-01-08	58.922 mi
Registration #8	2021-01-23	58.939 mi
Registration #9		11.777 es
Registration #10		77,777 66
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		9.777 no

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
CarChack so uk	nago 12/1:

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CFFB817289