



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-13
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-05
MOT pass rate	52 %
MOT passed	12
Failed MOT tests	11
Total advice items	99
Total items failed	9

MOT #23	2024-02-06 09:47
---------	------------------

MOT test number	784633843381
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-05
------------------	------------

Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm tread depth (5.2.3 (e))
Minor	Offside Windscreen damaged but not adversely affecting driver's view cracked (3.2 (a) (i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))



MOT #222024-01-25 12:52

MOT test number721862885580

Result

Failed

- Advice

Exhaust has a minor leak of exhaust gases heatshield loose (6.1.2 (a))
- Minor

Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR

Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #21

2024-01-16 09:49

MOT test number

299072907887

Result

✗ Failed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR Brake fluid significantly below minimum mark (1.1.10 (d) (ii))

Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MAJOR Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MAJOR Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

DANGEROUS Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Exhaust has a minor leak of exhaust gases heatshield loose (6.1.2 (a))

MAJOR Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

DANGEROUS Offside Rear Brake disc in such a condition that it is seriously weakened scored (1.1.14 (a) (ii))

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))



MOT #202023-01-26 15:23

MOT test number125811550837

Result

✓ Passed

- Advice

Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #19**

2023-01-26 10:47

MOT test number

807923704675

Result**✗ Failed****Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #18**

2022-01-24 15:26

MOT test number

763193353709

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2022-01-12 11:34

MOT test number

712703314008

Result**✗ Failed**

MAJOR Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

MAJOR Nearside Rear Suspension component pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

**MOT #16**

2021-09-18 10:54

MOT test number

519416060844

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm. remaining (5.2.3 (e))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 see emissions printout (8.2.2.2 (b))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened worn/lipped on both faces (1.1.14 (a) (ii))**MAJOR** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Both rear tyres are wearing unevenly on inner edges! advise wheel alignment check/adjust**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened worn/lipped on both faces (1.1.14 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm. remaining (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened worn/lipped on both faces (1.1.14 (a) (ii))**MAJOR** Exhaust emissions likely to be affected by an exhaust leak rear silencer is corroded and holed ! requires welding or replacement (8.2.2.1 (b))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened worn/lipped on both faces (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15**

2020-10-03 10:13

MOT test number

533933355285

Result

✓ Passed

MOT #14

2020-10-03 07:55

MOT test number

496826871713

Result

✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm. remaining (5.2.3 (e))

**MOT #13**

2019-10-05 08:28

MOT test number

899863980398

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 3.0mm also wearing inner edge (5.2.3 (e))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3.0mm also wearing inner edge (5.2.3 (e))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #12

2019-10-05 08:28

MOT test number

441012332109

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge 3.0mm also wearing inner edge (5.2.3 (e))

Pass with rectification Nearside Side repeater not working (4.4.1 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3.0mm also wearing inner edge (5.2.3 (e))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #11

2018-10-13 09:13

MOT test number

998291154291

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2018-10-13 08:22**MOT test number** 800105307097**Result** ✗ Failed**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2017-10-02 13:14**MOT test number** 633847344097**Result** ✓ Passed**MOT #8** 2017-10-02 08:52**MOT test number** 700414573036**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Pass with rectification** Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)**MOT #7** 2016-09-30 10:47**MOT test number** 342418593809**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-10-15 15:53**MOT test number** 623050203968**Result** ✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement slight (2.4.G.2)

MOT #5 2015-10-15 14:30**MOT test number** 648783733579**Result** ✗ Failed

Fail Exhaust has a major leak of exhaust gases mid pipe (7.1.2)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement slight (2.4.G.2)

MOT #4 2014-07-24 16:02**MOT test number** 419535804245**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-07-23 11:57**MOT test number** 245104504276**Result** ✗ Failed

Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-08-02 11:09
MOT test number	405564313272
Result	✓ Passed

MOT #1	2013-08-01 10:45
MOT test number	538013013279
Result	✗ Failed
Fail	Exhaust emits an excessive level of metered smoke (7.4.B.3a)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
5 February 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	5 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	WV60FLL
Plate since	2019-09-29
Current registration	WV60FLL
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2010-09-18
Last registration	2024-02-06
Complete history	See info



Registration #1	2010-09-18	18 mi
Registration #2	2013-08-01	34.948 mi
Registration #3	2013-08-02	34.958 mi
Registration #4	2014-07-23	44.803 mi
Registration #5	2014-07-24	44.803 mi
Registration #6	2015-10-15	61.195 mi
Registration #7	2015-10-15	61.195 mi
Registration #8	2016-09-30	74.479 mi
Registration #9	2017-10-02	87.158 mi
Registration #10	2017-10-02	87.158 mi
Registration #11	2018-10-13	99.880 mi
Registration #12	2018-10-13	99.830 mi
Registration #13	2019-10-05	112.820 mi
Registration #14	2019-10-05	112.820 mi
Registration #15	2019-10-05	112.820 mi
Registration #16	2019-10-05	112.820 mi
Registration #17	2019-10-05	112.820 mi
Registration #18	2019-10-05	112.820 mi
Registration #19	2019-10-05	112.820 mi
Registration #20	2019-10-05	112.820 mi
Registration #21	2019-10-05	112.820 mi
Registration #22	2019-10-05	112.820 mi
Registration #23	2019-10-05	112.820 mi
Registration #24	2019-10-05	112.820 mi
Registration #25	2019-10-05	112.820 mi



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080