



ST57NGZ

report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Blue
Year of manufacture	2007
Top speed	113 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 3

Date 2023-06-13

Pictures 12

Listing price [View report](#)



source: cargurus.co.uk

Entry 2

Date 2021-09-19

Pictures 23

Listing price [View report](#)



source: autotrader.co.uk

Entry 1

Date 2021-09-19

Pictures 14

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-23
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	32
Total items failed	13

MOT #16	2023-05-24 15:25
MOT test number	471737187094
Result	✓ Passed
Next expiry date	2024-05-23
Advice	Front Steering linkage ball joint has slight play both inner (2.1.3 (b) (i))
Advice	Vehicle underbody multiple suspension corroded and undersealed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2021-08-05 15:11
MOT test number	592321230274
Result	✓ Passed

MOT #14	2021-08-05 15:11
MOT test number	858262283985
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #13

2020-01-03 18:30

MOT test number

563596147745

Result

✓ Passed

- Advice

Child Seat fitted not allowing full inspection of adult belt
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Fuel Pipe/s corroded
- Advice

Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #12**

2019-12-30 14:57

MOT test number

845800144381

Result**✗ Failed**

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))
- Advice** Low on engine oil
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Rear Brake performance not tested brake hose leaking (1.2.1 (g))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Fuel Pipe/s corroded
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #11

2018-12-12 17:14

MOT test number

574555117446

Result**✓ Passed**

- Advice** Both rear tyres slightly cracking 205/55/16
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #10** 2017-12-11 16:06**MOT test number** 783329250474**Result** ✓ Passed**MOT #9** 2016-12-01 11:53**MOT test number** 479577024733**Result** ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #8 2015-12-08 15:21**MOT test number** 435193415407**Result** ✓ Passed**MOT #7** 2014-12-09 14:39**MOT test number** 328893244315**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-12-09 11:02**MOT test number** 768933244327**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-12-11 16:29**MOT test number** 496505343382**Result** ✓ Passed**MOT #4** 2013-12-11 16:29**MOT test number** 469455043370**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2012-12-06 10:03**MOT test number** 735501542383**Result** ✓ Passed**MOT #2** 2011-12-13 11:26**MOT test number** 988497141366**Result** ✓ Passed**MOT #1** 2010-12-04 11:07**MOT test number** 130208030324**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
23 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-30
Last registration	2023-05-24
Complete history	See info



Registration #1	2007-11-30	18 mi
Registration #2	2010-12-04	36.267 mi
Registration #3	2011-12-13	43.928 mi
Registration #4	2012-12-06	51.847 mi
Registration #5	2013-12-11	60.182 mi
Registration #6	2014-12-09	68.470 mi
Registration #7	2014-12-09	68.470 mi
Registration #8	2015-12-08	75.697 mi
Registration #9	2016-12-01	84.066 mi
Registration #10	2017-12-11	91.127 mi
Registration #11	2018-05-22	91.127 mi
Registration #12	2018-05-22	91.127 mi
Registration #13	2018-05-22	91.127 mi
Registration #14	2018-05-22	91.127 mi
Registration #15	2018-05-22	91.127 mi
Registration #16	2018-05-22	91.127 mi
Registration #17	2018-05-22	91.127 mi
Registration #18	2018-05-22	91.127 mi
Registration #19	2018-05-22	91.127 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1512 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20217257