



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 POWERPULSE INSCRIPTION AWD
Colour	Silver
Year of manufacture	2018
Top speed	137 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	35.3 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-08
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #5	2023-10-02 10:15
MOT test number	998900535936
Result	✓ Passed
Next expiry date	2024-10-24
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4	2022-10-25 15:09
MOT test number	921570710620
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #3**

2022-10-06 11:10

MOT test number

233885124992

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Front Exhaust fumes causing a danger to health of persons on board (6.1.2 (b) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

2021-10-06 14:58

MOT test number

883781848900

Result

✓ Passed

- Advice** Engine undercover fitted obscuring some underside components

MOT #1

2021-02-03 10:20

MOT test number

442265687022

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YN18URG
Plate since	2019-03-28
Current registration	YN18URG
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-01
Last registration	2023-10-02
Complete history	See info



Registration #1	2018-03-01	21 mi
Registration #2	2021-02-03	18.007 mi
Registration #3	2021-10-06	22.670 mi
Registration #4	2023-05-29	25.277 mi
Registration #5	2023-05-29	25.277 mi
Registration #6	2023-05-29	25.277 mi
Registration #7	2023-05-29	25.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Max. allowed weight	2750 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	2422425