




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-05-12
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-03-31
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	28
Total items failed	17

MOT #19	2023-03-20 11:09
MOT test number	603366875187
Result	✓ Passed
Next expiry date	2024-03-31

MOT #18	2022-04-01 12:25
MOT test number	883770595703
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-03-01 12:43
MOT test number	699035596952
Result	✓ Passed
Advice	Various suspension components corroded and perishing
Advice	Offside rear indicator bulb slightly discoloured
Advice	Various oil leaks around engine

**MOT #16** 2020-01-31 12:05**MOT test number** 897176559065**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15** 2019-02-08 09:02**MOT test number** 860665199983**Result** ✓ Passed**MOT #14** 2019-02-07 13:39**MOT test number** 581646682251**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #13** 2018-05-23 13:23**MOT test number** 616206887455**Result** ✓ Passed**MOT #12** 2018-05-18 13:37**MOT test number** 499709944380**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Outer sidewall (4.1.D.1a)**Advice** Nearside Rear Tyre slightly perished between treads

**MOT #11** 2017-04-10 14:16**MOT test number** 751912296321**Result** ✓ Passed**MOT #10** 2017-04-07 15:10**MOT test number** 340879753932**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2016-03-14 15:00**MOT test number** 770750509662**Result** ✓ Passed**Advice** Rear exhaust support bracket snapped**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside rear bumper damaged**MOT #8** 2016-03-14 11:34**MOT test number** 139023636021**Result** ✗ Failed**Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** Rear exhaust support bracket snapped**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Fail** Offside Front Tyre has ply or cords exposed outer wall (4.1.D.1b)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Nearside rear bumper damaged**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #7**

2015-01-09 09:11

MOT test number

958729605081

Result

✓ Passed

Notice

Damage offside rear bumper

MOT #6

2015-01-08 10:30

MOT test number

256648005099

Result

✗ Failed

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail

Offside Front coil spring broken (2.4.C.1a)

Notice

Damage offside rear bumper

Fail

Nearside Front Direction indicator incorrect colour (1.4.A.2f)

MOT #5

2013-08-23 17:40

MOT test number

158615133290

Result

✓ Passed

Notice

Exhaust mount broken but system still supported

MOT #4

2013-08-23 17:40

MOT test number

749255333230

Result

✗ Failed

Pass with rectification

Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification

Nearside Rear Seat belt retracting mechanism defective (5.2.5b)

Notice

Exhaust mount broken but system still supported

Pass with rectification

Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Pass with rectification

Offside Rear coil spring broken (2.4.C.1a)

**MOT #3** 2012-08-23 16:40**MOT test number** 368886232215**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Nearside front wiper smearing slightly**MOT #2** 2012-08-23 15:38**MOT test number** 836536532272**Result** ✗ Failed**Notice** Nearside front wiper smearing slightly**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #1** 2011-08-25 10:28**MOT test number** 795817431238**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2024

X

MOT

Expired:
31 March 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	31 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	AE58HHL
Plate since	2024-03-29
Current registration	AE58HHL
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-22
Last registration	2023-03-20
Complete history	See info



Registration #1	2008-09-22	19 mi
Registration #2	2011-08-25	25.933 mi
Registration #3	2012-08-23	36.612 mi
Registration #4	2012-08-23	36.621 mi
Registration #5	2013-08-23	46.423 mi
Registration #6	2015-01-08	52.962 mi
Registration #7	2015-01-09	52.965 mi
Registration #8	2016-03-14	58.791 mi
Registration #9	2016-03-14	58.794 mi
Registration #10	2017-04-07	65.970 mi
Registration #11	2019-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2019-05-20	75.377 mi
Registration #14	2019-05-20	75.377 mi
Registration #15	2019-05-20	75.377 mi
Registration #16	2019-05-20	75.377 mi
Registration #17	2019-05-20	75.377 mi
Registration #18	2019-05-20	75.377 mi
Registration #19	2019-05-20	75.377 mi
Registration #20	2019-05-20	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564