



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE ACENTA PREMIUM
Colour	Black
Year of manufacture	2014
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-06-11
Pictures	8
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-05-27
Pictures	37
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-12
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	23
Total items failed	4

MOT #9	2023-06-21 14:08
MOT test number	299759592357
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))

**MOT #8**

2023-06-20 14:28

**MOT test number**

281245471130

**Result**

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))

**MOT #7**

2022-06-29 13:00

**MOT test number**

123810678385

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Slightly perished (5.2.3 (d) (ii))

**MOT #6**

2021-07-13 15:28

**MOT test number**

814210105161

**Result**

✓ Passed

**MOT #5** 2020-11-28 10:12**MOT test number** 224231664226**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated leaking grease from under the securing clip but prevents the ingress of dirt (6.1.7 (g) (i))**MOT #4** 2019-11-23 09:31**MOT test number** 479941921503**Result** ✓ Passed**MOT #3** 2018-11-23 08:45**MOT test number** 506617889190**Result** ✓ Passed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both front lower arms front inner bushes starting to separate from their bonding (5.3.4 (a) (i))**MOT #2** 2017-11-28 16:29**MOT test number** 433231509442**Result** ✓ Passed**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #1	2017-11-25 10:24
MOT test number	551530402119
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Nearside Front Front wheel bearing has excessive play (2.5.A.3c)
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
12 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	12 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-02
Last registration	2023-06-21
Complete history	<a href="#">See info</a>



Registration #1	2014-12-02	25 mi
Registration #2	2017-11-25	19.965 mi
Registration #3	2017-11-28	20.028 mi
Registration #4	2018-11-23	26.158 mi
Registration #5	2019-11-23	30.799 mi
Registration #6	2020-11-28	33.801 mi
Registration #7	2020-11-28	33.801 mi
Registration #8	2020-11-28	33.801 mi
Registration #9	2020-11-28	33.801 mi
Registration #10	2020-11-28	33.801 mi
Registration #11	2020-11-28	33.801 mi
Registration #12	2020-11-28	33.801 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1036 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	068355R