



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 SE LUX D S40
Colour	Black
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-07
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-05
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	47
Total items failed	9

MOT #18	2023-10-06 10:45
MOT test number	939218432326
Result	✓ Passed
Next expiry date	2024-10-05
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Front Items removed from driver's view prior to test

MOT #17	2022-10-05 11:21
MOT test number	776004307824
Result	✓ Passed
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear. (1.1.11 (c))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear. (1.1.11 (c))

**MOT #16**

2022-09-30 11:46

MOT test number

767309075978

Result**✗ Failed**

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #15

2021-09-28 14:13

MOT test number

370447425565

Result**✓ Passed****MOT #14**

2021-09-28 11:30

MOT test number

270348224415

Result**✗ Failed**

- DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Pass with rectification** Headlamp light source and lamp not compatible n/s and o/s (4.1.4 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge (5.2.3 (e))

**MOT #13**

2021-03-09 16:18

MOT test number

520918666160

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust system deteriorated**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2021-03-08 15:52

MOT test number

905526628704

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Upper Shock absorbers insecurely attached Attachment bracket / mounting broken (5.3.2 (a) (i))**MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust system deteriorated**MOT #11**

2020-03-12 15:58

MOT test number

837660405216

Result

✓ Passed

MOT #10

2018-11-29 08:44

MOT test number

564690197771

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s (5.3.4 (a) (i))

**MOT #9** 2017-12-27 09:28**MOT test number** 174251416773**Result** ✓ Passed**MOT #8** 2016-11-15 16:00**MOT test number** 743591054440**Result** ✓ Passed

- Advice** Exhaust centre silensor corroded
- Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement offside and nearside front wishbones rear bushes (2.4.G.2)
- Advice** Brake pedal rubber missing but has anti slip
- Advice** Exhaust heatshield insecure

MOT #7 2016-11-14 11:04**MOT test number** 413667222861**Result** ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)
- Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Exhaust heatshield insecure
- Advice** Exhaust centre silensor corroded
- Fail** Body has a sharp edge caused by damage offside wing mirror (6.1.C.1)
- Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer wall (4.1.D.1a)
- Fail** Nearside Rear reflector excessively deteriorated so that its function is impaired (1.5.1c)
- Advice** Brake pedal rubber missing but has anti slip
- Fail** Offside Side repeater not working no bulb (1.4.A.2c)
- Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement offside and nearside front wishbones rear bushes (2.4.G.2)



MOT #6 2015-07-18 11:47

MOT test number 985749795142

Result ✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2014-05-23 13:05

MOT test number 199213744105

Result ✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2013-06-13 16:01

MOT test number 988134263194

Result ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Under-trays fitted obscuring some underside components

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Engine covers fitted obscuring some components in the engine bay

**MOT #3** 2013-06-05 13:20**MOT test number** 747026153128**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Exhaust has part of system slightly deteriorated**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front coil spring fractured (2.4.C.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2013-03-28 15:20**MOT test number** 457637483003**Result** ✓ Passed**MOT #1** 2011-11-08 12:50**MOT test number** 467702611495**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-11-20
Last registration	2023-10-06
Complete history	See info



Registration #1	2008-11-20	6 mi
Registration #2	2011-11-08	47.038 mi
Registration #3	2013-03-28	53.322 mi
Registration #4	2013-06-05	54.014 mi
Registration #5	2013-06-13	54.016 mi
Registration #6	2014-05-23	57.531 mi
Registration #7	2015-07-18	59.245 mi
Registration #8	2016-11-14	62.303 mi
Registration #9	2016-11-15	62.304 mi
Registration #10	2017-12-27	64.767 mi
Registration #11	2018-01-01	65.000 mi
Registration #12	2018-01-01	65.000 mi
Registration #13	2018-01-01	65.000 mi
Registration #14	2018-01-01	65.000 mi
Registration #15	2018-01-01	65.000 mi
Registration #16	2018-01-01	65.000 mi
Registration #17	2018-01-01	65.000 mi
Registration #18	2018-01-01	65.000 mi
Registration #19	2018-01-01	65.000 mi
Registration #20	2018-01-01	65.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	411629