





report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Silver
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

Date	2021-10-21	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT history

MOT #6	2014-04-07 17:35
MOT test number	469467794095
Result	✓ Passed
Next expiry date	2015-04-06
Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	

MOT #5

MOT test number

757822153246

Result

Advice Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Centre Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #4		2012-09-11 09:11
MOT test	number	287185852282
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Oil leak from gearbox	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2011-08-24 10:27
MOT test number	876206931213
Result	✓ Passed
Notice Slight oil leak from gearbox area	

MOT #2	2010-09-08 12:36
MOT test number	451831850205
Result	✓ Passed

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT #1 2010-09-02 11:43 **MOT test number** 941525740281 Result × Failed **Notice** OUTER COATING SPLITTING AWAY FROM REAR EXHAUST BOX Fail Offside Rear Stop lamp not working (1.2.1b) Notice REAR BRAKE PADS ON AROUND 2.5MM Advice Nearside front brake juddering slightly (3.7.A.2b) Notice REAR EXHAUST MOUNTING RUBBER SPLITTING Fail Front Exhaust has part of the system excessively deteriorated (7.1.1a) **Advice** Offside front brake juddering slightly (3.7.A.2b)

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	

THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIX
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2007-07-31
Last registration	2014-04-07
Complete history	See info



Registration #1	2007-07-31	14 mi
Registration #2	2010-09-02	46.627 mi
Registration #3	2010-09-08	46.627 mi
Registration #4	2011-08-24	61.495 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/1

Number of axles 2
Engine number 1188390