



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Silver
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-07-21
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-04
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	38
Total items failed	5

MOT #16	2023-06-05 13:12
MOT test number	187138838481
Result	✓ Passed
Next expiry date	2024-06-04
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2022-07-20 16:30
MOT test number	924616034250
Result	✓ Passed

MOT #14	2021-10-29 15:31
MOT test number	324406959459
Result	✓ Passed
Advice	Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
Advice	Offside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))

MOT #13	2020-10-13 09:27
MOT test number	587158887515
Result	✓ Passed

**MOT #12**

2020-10-13 08:39

MOT test number

324310538917

Result**✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11**

2019-04-23 11:58

MOT test number

140983515491

Result**✓ Passed****Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** General underside corrosion**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Spring's rusty**MOT #10**

2019-04-23 11:58

MOT test number

126228467431

Result**✗ Failed****Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** General underside corrosion**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Spring's rusty**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #9** 2018-04-24 13:59**MOT test number** 429044178588**Result** ✓ Passed

- Advice** Rear exhaust hangers corroded
- Advice** Body has slight corrosion under vehicle by seals (6.1.B.2)
- Advice** Offside Rear tyre perishing in tread
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear tyre perishing in tread
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #8 2017-04-12 10:29**MOT test number** 236465290872**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2016-07-21 10:14**MOT test number** 378723398668**Result** ✓ Passed

- Advice** Brake pad(s) wearing thin (3.5.1g)
- Advice** Brake pipe slightly corroded both rear at flexi (3.6.B.2c)
- Advice** Rear exhaust metal brackets corroding and getting thin
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front wipers starting to smear



MOT #6	2015-07-15 09:24
MOT test number	969196695101
Result	✓ Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #5	2015-07-15 09:24
MOT test number	975916195178
Result	✗ Failed
Pass with rectification	Nearside Front Direction indicators incorrect colour (1.4.A.2f)
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Pass with rectification	Offside Front Direction indicators incorrect colour (1.4.A.2f)

MOT #4	2014-07-16 12:24
MOT test number	909507994163
Result	✓ Passed
Notice	Both rear tyres are miss shaped on the inner edges
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2013-07-26 12:44
MOT test number	599037903278
Result	✓ Passed
Notice	Both rear tyres feathering on inner edges
Notice	Front wipers smear/judder



MOT #2	2012-07-12 12:42
MOT test number	626524792191
Result	✓ Passed
Notice	Both rear tyres are starting to miss shape on the inner edges

MOT #1	2011-07-19 09:38
MOT test number	446000601261
Result	✓ Passed
Notice	Both rear tyres feathered
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓

Taxed

Tax due:
1 July 2024

✓

MOT

Expires:
4 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	4 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-07-30
Last registration	2023-06-05
Complete history	See info



Registration #1	2008-07-30	25 mi
Registration #2	2011-07-19	24.169 mi
Registration #3	2012-07-12	34.089 mi
Registration #4	2013-07-26	41.595 mi
Registration #5	2014-07-16	47.085 mi
Registration #6	2015-07-15	54.454 mi
Registration #7	2016-07-21	62.331 mi
Registration #8	2017-04-12	66.193 mi
Registration #9	2018-04-24	76.531 mi
Registration #10	2019-05-20	85.377 mi
Registration #11	2020-05-20	95.377 mi
Registration #12	2021-05-20	105.377 mi
Registration #13	2022-05-20	115.377 mi
Registration #14	2023-05-20	125.377 mi
Registration #15	2024-05-20	135.377 mi
Registration #16	2025-05-20	145.377 mi
Registration #17	2026-05-20	155.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZV035065