



HONDA




report date: 2024-03-28

General information

Make	HONDA
Model	CIVIC I-DTEC S TOURER
Colour	White
Year of manufacture	2014
Top speed	121 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	8
Total items failed	5

MOT #11	2024-01-09 13:30
MOT test number	604693763620
Result	✓ Passed
Next expiry date	2025-01-19
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2023-01-20 11:06
MOT test number	733227091916
Result	✓ Passed

MOT #9	2022-01-17 10:48
MOT test number	958222590075
Result	✓ Passed

MOT #8	2021-02-25 15:55
MOT test number	733098914631
Result	✓ Passed

**MOT #7** 2021-02-25 15:55**MOT test number** 738374890339**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2020-12-15 10:15**MOT test number** 736376955119**Result** ✓ Passed**MOT #5** 2019-10-16 15:53**MOT test number** 581517047396**Result** ✓ Passed**MOT #4** 2019-10-15 10:22**MOT test number** 403442203376**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2018-10-10 11:37**MOT test number** 290530033632**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #2	2018-10-08 10:34
MOT test number	201654275398
Result	✗ Failed
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Central Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

MOT #1	2017-09-28 09:17
MOT test number	710559456664
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 January 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	19 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-20
Current registration	
Plate since	2019-06-20

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-30
Last registration	2024-01-09
Complete history	See info



Registration #1	2014-09-30	9 mi
Registration #2	2017-09-28	29.577 mi
Registration #3	2018-10-08	44.325 mi
Registration #4	2018-10-10	44.325 mi
Registration #5	2019-10-15	58.141 mi
Registration #6	2019-10-16	44.327 mi
Registration #7	2020-12-15	65.677 mi
Registration #8	2020-05-20	55.277 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	83%
Pedestrian	69%
Safety systems	86%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2065 mm
Height	1480 mm
Length	4300 mm
Kerb weight	1430 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A12012323