



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX ZETEC CLI. D
Colour	Black
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	242 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	58.9 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-03
Pictures	60
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #17**

2021-11-23 14:56

MOT test number

129220800918

Result

✓ Passed

Next expiry date

2022-11-22

Advice

Sub-frame corroded but not seriously weakened both ends and various suspension components (5.3.3 (b) (i))

Minor

Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Front Direction indicator slightly discoloured (4.4.3 (a))

Advice

Rear Coil spring corroded both sides (5.3.1 (b) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Fuel tank heatshield slightly insecure but not affecting safety

**MOT #16**

2021-11-17 12:48

MOT test number

723113821655

Result

✗ Failed

- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Fail** Emissions not tested (8.2.2.2 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Fuel tank heatshield slightly insecure but not affecting safety
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Sub-frame corroded but not seriously weakened both ends and various suspension components (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values pv 2.50 first rev 5.6 ! (8.2.2.2 (f))
- Advice** Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15

2020-10-30 09:51

MOT test number

936327042262

Result

✓ Passed

- Advice** Offside Front All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Nearside Front All direction indicators slightly discoloured (4.4.3 (a))

**MOT #14** 2019-10-31 10:43**MOT test number** 337916112005**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** All direction indicators slightly discoloured (4.4.3 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2018-11-14 12:03**MOT test number** 190268153676**Result** ✓ Passed**MOT #12** 2017-11-15 10:52**MOT test number** 493145638089**Result** ✓ Passed**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #11** 2016-11-09 11:41**MOT test number** 394015212359**Result** ✓ Passed**MOT #10** 2015-11-16 12:20**MOT test number** 307936298591**Result** ✓ Passed

**MOT #9** 2014-11-17 17:09**MOT test number** 929491124386**Result** ✓ Passed**MOT #8** 2013-11-19 11:20**MOT test number** 367793923395**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2013-11-18 16:36**MOT test number** 939132023309**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2012-10-16 14:35**MOT test number** 835480092218**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/f tyre is worn to excess on inner edge. n/s/r tyre is perished and cracking.

**MOT #5** 2012-10-12 14:58**MOT test number** 876656282284**Result** ✗ Failed**Fail** Centre Rear Passenger's seat cannot be secured in the upright position. (6.2.A.2)**Notice** N/s/f tyre is worn to excess on inner edge. n/s/r tyre is perished and cracking.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-10-03 11:07**MOT test number** 475526571257**Result** ✓ Passed**MOT #3** 2010-11-02 13:07**MOT test number** 513176300394**Result** ✓ Passed**MOT #2** 2010-04-27 12:38**MOT test number** 121917210130**Result** ✓ Passed**MOT #1** 2009-04-02 15:08**MOT test number** 911122799052**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YE06AEX
Plate since	2019-09-29
Current registration	YE06AEX
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-05-19
Last registration	2021-11-23
Complete history	See info



Registration #1	2006-05-19	25 mi
Registration #2	2009-04-02	29.469 mi
Registration #3	2010-04-27	34.686 mi
Registration #4	2010-11-02	36.438 mi
Registration #5	2011-10-03	39.943 mi
Registration #6	2012-10-12	43.317 mi
Registration #7	2012-10-16	43.389 mi
Registration #8	2013-11-18	49.503 mi
Registration #9	2013-11-19	49.504 mi
Registration #10	2014-11-17	58.507 mi
Registration #11	2015-05-20	59.377 mi
Registration #12	2015-05-20	59.377 mi
Registration #13	2015-05-20	59.377 mi
Registration #14	2015-05-20	59.377 mi
Registration #15	2015-05-20	59.377 mi
Registration #16	2015-05-20	59.377 mi
Registration #17	2015-05-20	59.377 mi
Registration #18	2015-05-20	59.377 mi
Registration #19	2015-05-20	59.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1370 kg
Max. allowed weight	1795 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6U84977