



TOYOTA

**GY54POU**

report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVTI T3
Colour	Silver
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg





Internet history

Entry 2

Date	2021-12-12
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-08-15
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

**MOT history**

<b>MOT #20</b>	2021-12-09 10:35
<b>MOT test number</b>	131808400249
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-12-08
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Brake disc worn, pitted or scored, but not seriously weakened both rear on inner face (1.1.14 (a) (ii))

<b>MOT #19</b>	2021-12-01 14:58
<b>MOT test number</b>	612226153523
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Electronic stability control warning lamp indicates a fault (7.12 (e))
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>MAJOR</b>	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
<b>Advice</b>	Brake disc worn, pitted or scored, but not seriously weakened both rear on inner face (1.1.14 (a) (ii))
<b>MAJOR</b>	Front Service brake excessively fluctuating (1.2.1 (e))
<b>Advice</b>	Rear exhaust bracket insecure
<b>MAJOR</b>	Position lamp not working both front (4.2.1 (a) (ii))
<b>Advice</b>	Brake disc worn, pitted or scored, but not seriously weakened both front on inner face (1.1.14 (a) (ii))

<b>MOT #18</b>	2020-09-24 11:40
<b>MOT test number</b>	101418414349
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

**MOT #17** 2020-09-23 18:18**MOT test number** 958119973925**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**MOT #16** 2019-11-21 11:16**MOT test number** 513486238130**Result** ✓ Passed**MOT #15** 2018-11-06 09:02**MOT test number** 339623148991**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #14** 2017-11-06 11:09**MOT test number** 649082222827**Result** ✓ Passed**MOT #13** 2016-11-03 13:13**MOT test number** 717588263173**Result** ✓ Passed**Advice** Front front wiper blades need replacing**Advice** Brake pad(s) wearing thin pads low need replacing (3.5.1g)

**MOT #12** 2015-11-03 15:42**MOT test number** 837568494381**Result** ✓ Passed**MOT #11** 2014-11-06 15:14**MOT test number** 776340814387**Result** ✓ Passed**MOT #10** 2014-11-06 15:14**MOT test number** 889560914358**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2013-10-30 10:17**MOT test number** 319383803314**Result** ✓ Passed**MOT #8** 2012-10-31 17:02**MOT test number** 939535002316**Result** ✓ Passed**MOT #7** 2012-10-31 09:52**MOT test number** 957385202399**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2011-11-01 10:09**MOT test number** 779815701320**Result** ✓ Passed**MOT #5** 2010-11-03 09:28**MOT test number** 874837700358**Result** ✓ Passed**Notice** Both rear tyres wearing on edges n/s worst.**MOT #4** 2009-10-03 10:08**MOT test number** 360136779466**Result** ✓ Passed**Notice** Offside wing mirror glass cracked**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside front wiper blade split**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-10-03 10:08**MOT test number** 793286779235**Result** ✗ Failed**Notice** Offside wing mirror glass cracked**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Offside front wiper blade split**Advice** Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2008-10-03 11:43
MOT test number	490007678210
Result	✓ Passed
MOT #1	2007-10-08 13:51
MOT test number	240701387286
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-10-07
Last registration	2021-12-09
Complete history	<a href="#">See info</a>



Registration #1	2004-10-07	29 mi
Registration #2	2007-10-08	31.038 mi
Registration #3	2008-10-03	42.038 mi
Registration #4	2009-10-03	50.383 mi
Registration #5	2010-11-03	59.767 mi
Registration #6	2011-11-01	68.105 mi
Registration #7	2012-10-31	74.990 mi
Registration #8	2012-10-31	74.990 mi
Registration #9	2013-10-30	82.692 mi
Registration #10	2014-11-06	90.541 mi
Registration #11	2015-11-03	99.036 mi
Registration #12	2016-10-30	107.531 mi
Registration #13	2017-10-29	116.026 mi
Registration #14	2018-10-28	124.521 mi
Registration #15	2019-10-27	133.016 mi
Registration #16	2020-10-26	141.511 mi
Registration #17	2021-10-25	150.006 mi
Registration #18	2022-10-24	158.501 mi
Registration #19	2023-10-23	166.996 mi
Registration #20	2024-10-22	175.491 mi
Registration #21	2025-10-21	183.986 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1ZZE184784