



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN FSI SPORT 7 STR
Colour	Black
Year of manufacture	2004
Top speed	125 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	200 Nm at 3.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	194 g/km
CO2 label	J








Internet history

Entry 1

Date	2021-06-18
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-10-07
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #17	2020-10-06 11:43
MOT test number	263266260575
Result	✓ Passed
Next expiry date	2021-10-07

MOT #16	2019-10-08 12:15
MOT test number	243738085710
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15	2018-06-16 15:38
MOT test number	833706263141
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #14	2017-05-19 08:28
MOT test number	683013352159
Result	✓ Passed
Advice	Under trays fitted,unable to check some components



MOT #13	2016-06-02 14:38
MOT test number	341259913063
Result	✓ Passed
Advice	Engine covers & under trays fitted,unable to check some components
Advice	N/s/r tyre worn on inside edge

MOT #12	2016-06-02 08:31
MOT test number	884459312569
Result	✗ Failed
Advice	Engine covers & under trays fitted,unable to check some components
Advice	N/s/r tyre worn on inside edge
Fail	Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #11	2015-05-29 11:51
MOT test number	425459145128
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #10	2014-05-22 14:52
MOT test number	108952044111
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components

MOT #9	2013-05-16 14:47
MOT test number	839486033172
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components

**MOT #8** 2012-05-25 12:04**MOT test number** 209076542478**Result** ✓ Passed**Notice** Unable to see full condition of brake and fuel pipes owing to covers fitted to underside of vehicle**MOT #7** 2011-05-20 09:43**MOT test number** 685730141106**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2010-05-20 15:00**MOT test number** 232610440495**Result** ✓ Passed**Notice** Both front lower arm rear bushes starting to split**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-06-05 10:54**MOT test number** 202276159134**Result** ✓ Passed**MOT #4** 2009-06-05 10:54**MOT test number** 100516559107**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)



MOT #3	2008-05-22 10:59
MOT test number	732393648197
Result	✓ Passed

MOT #2	2008-05-22 10:59
MOT test number	114493248187
Result	✗ Failed
<div>Pass with rectification</div> Rear Registration plate lamp not working (1.1.5c)	

MOT #1	2007-06-04 11:52
MOT test number	651335557149
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
21 March 2021

✕
MOT

Expired:
7 October 2021

Tax status	Expired at 21 March 2021
Days left	1135 days too late
MOT expiry date	7 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BD04ETZ
Plate since	2019-09-29
Current registration	 BD04ETZ
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2004-06-08
Last registration	2020-10-06
Complete history	See info



Registration #1	2004-06-08	15 mi
Registration #2	2007-06-04	19.375 mi
Registration #3	2008-05-22	26.637 mi
Registration #4	2009-06-05	34.964 mi
Registration #5	2010-05-20	44.072 mi
Registration #6	2011-05-20	52.526 mi
Registration #7	2012-05-25	61.668 mi
Registration #8	2013-05-16	71.257 mi
Registration #9	2014-05-22	81.577 mi
Registration #10	2015-05-22	91.897 mi
Registration #11	2016-05-22	102.217 mi
Registration #12	2017-05-22	112.537 mi
Registration #13	2018-05-22	122.857 mi
Registration #14	2019-05-22	133.177 mi
Registration #15	2020-05-22	143.497 mi
Registration #16	2021-05-22	153.817 mi
Registration #17	2022-05-22	164.137 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1509 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	AXW 020731