






report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI KX-2
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/10



Internet history

Entry 1

Date 2021-07-10


Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-03-06
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #7	2023-03-07 13:03
MOT test number	821566374264
Result	✓ Passed
Next expiry date	2024-03-06
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #6	2022-03-04 14:56
MOT test number	344947959495
Result	✓ Passed

MOT #5	2021-02-27 10:53
MOT test number	462366639366
Result	✓ Passed

MOT #4	2020-02-10 12:43

MOT test number 930805282939
Result ✓ Passed

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

CarCheck.co.uk page 3/10



MOT #3 2019-02-15 12:01

MOT test number 927608820879

Result Passed

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

MOT #2 2018-02-10 10:45

MOT test number 674736496310

Result

Passed

Advice Nearside Front tyre perished

MOT #1 2017-02-23 11:18

MOT test number 484271838656

Result \rightarrow Passed

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	

THE STATE OF THE S	
HEREER PARTY AND ADDRESS OF THE PARTY AND ADDR	

THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-03-03
Last registration	2023-03-07
Complete history	See info



Registration #1	2014-03-03	13 mi
Registration #2	2017-02-23	19.677 mi
Registration #3	2018-02-10	22.036 mi
Registration #4	2019-02-15	24.770 mi
Registration #5	2020-02-10	26.554 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1700 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1891 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 10/10

Engine number

D4HBDH092511