



 **MK6IFVL**

report date: 2024-03-29

General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 100 km/h	11.1 seconds
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-10-26
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	52
Total items failed	11

## MOT #15 2023-10-27 14:43

MOT test number 992086590901

Result ✓ Passed

Next expiry date 2024-10-26

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Also perishing within tread blocks. (5.2.3 (e))
- Advice** Nearside Front Mirror damaged and taped up to secure.
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Also perishing within tread blocks. (5.2.3 (e))

## MOT #14 2022-10-04 07:58

MOT test number 602190160162

Result ✓ Passed

- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #13**

2022-10-03 12:36

**MOT test number**

385688445524

**Result****✗ Failed****Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**MOT #12**

2021-10-19 13:37

**MOT test number**

577523614110

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge badly worn on outer tread area (5.2.3 (e))**Advice** Front Inner Brake pad(s) wearing thin wearing low (1.1.13 (a) (ii))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces of discs corroded and worn (1.1.14 (a) (ii))**MOT #11**

2021-10-19 11:32

**MOT test number**

461411173897

**Result****✗ Failed**

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces of discs corroded and worn (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge badly worn on outer tread area (5.2.3 (e))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Front Inner Brake pad(s) wearing thin wearing low (1.1.13 (a) (ii))

**Fail** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**MOT #10** 2020-10-20 18:09**MOT test number** 842615438245**Result** ✓ Passed**MOT #9** 2020-10-19 12:40**MOT test number** 786091189690**Result** ✗ Failed

- Fail** Front Exhaust system insecure BRACKET (6.1.2 (a))
- Advice** Offside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2020-01-27 17:18**MOT test number** 497207208397**Result** ✓ Passed

- Advice** Covers and under trays fitted to this vehicle preventing the full inspection of some components.
- Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #7** 2020-01-27 09:50**MOT test number** 464737955167**Result** ✗ Failed

- Advice** Brake disc worn, but not excessively All brake discs worn. (1.1.14 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** Covers and under trays fitted to this vehicle preventing the full inspection of some components.
- Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #6** 2019-01-28 10:04**MOT test number** 571614107758**Result** ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Tyre obviously under inflated (5.2.3 (h) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Covers and under trays fitted to this vehicle preventing the full inspection of some components.
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2018-01-24 09:13**MOT test number** 606282723822**Result** ✓ Passed

- Advice** Covers fitted
- Advice** Rear tires slightly perished

**MOT #4**

2018-01-23 09:25

**MOT test number**

616179128508

**Result**

✗ Failed

**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement front most bush starting to delaminate (2.4.G.2)**Advice** Rear tires slightly perished**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement front most bush delaminated (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Covers fitted**MOT #3**

2017-01-19 10:03

**MOT test number**

581486347701

**Result**

✓ Passed

**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement Starting to seperate (2.4.G.2)**Advice** Emissions too low to obtain a reading**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Play in steering rack inner joint(s)**Advice** Both rear tyres perished and wearing on shoulders**Advice** Under trays fitted obscuring some testable components**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #2**

2016-01-29 08:51

**MOT test number**

230246949809

**Result**

✓ Passed

**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)





MOT #1	2015-01-05 14:47
MOT test number	925095005069
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-01-31
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2012-01-31	21 mi
Registration #2	2015-01-05	28.578 mi
Registration #3	2016-01-29	46.603 mi
Registration #4	2017-01-19	48.500 mi
Registration #5	2018-01-23	59.581 mi
Registration #6	2018-01-24	59.581 mi
Registration #7	2019-01-28	70.933 mi
Registration #8	2020-01-27	81.278 mi
Registration #9	2020-01-27	81.278 mi
Registration #10	2020-01-27	81.278 mi
Registration #11	2020-01-27	81.278 mi
Registration #12	2020-01-27	81.278 mi
Registration #13	2020-01-27	81.278 mi
Registration #14	2020-01-27	81.278 mi
Registration #15	2020-01-27	81.278 mi
Registration #16	2020-01-27	81.278 mi
Registration #17	2020-01-27	81.278 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1631 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2



Engine number	BS48457
---------------	---------