



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 CRDI SE NAV
Colour	Blue
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 2

Date	2023-05-06
Pictures	50
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-01-31
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-10
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #7	2024-04-08 11:17
MOT test number	476427978028
Result	✓ Passed
Next expiry date	2025-04-10
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 225/45r17 (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6**

2024-04-05 13:08

MOT test number

903701370400

Result

✗ Failed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 225/45r17 (5.2.3 (e))

MOT #5

2023-04-11 10:02

MOT test number

679355691081

Result

✓ Passed

MOT #4

2022-09-02 13:02

MOT test number

709290145162

Result

✓ Passed

**MOT #3** 2022-09-01 12:56**MOT test number** 163794131591**Result** ✗ Failed**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Tyre has ply or cords exposed 225/45/17 (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge flat spotted (5.2.3 (e))**MOT #2** 2021-09-13 08:53**MOT test number** 626993073555**Result** ✓ Passed**MOT #1** 2020-09-10 14:30**MOT test number** 332202515076**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	YS67DNV
Plate since	2019-03-29
Current registration	YS67DNV
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-11-25
Last registration	2024-04-08
Complete history	See info



Registration #1	2017-11-25	12 mi
Registration #2	2020-09-10	21.684 mi
Registration #3	2021-09-13	25.410 mi
Registration #4	2022-09-01	32.438 mi
Registration #5		
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1455 mm
Length	4340 mm
Wheel base	2650 mm
Kerb weight	1411 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBHZ169078