



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-08-29
Pictures	8
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-28
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-01
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	13
Total items failed	11

MOT #14	2023-08-14 09:32
MOT test number	327373639362
Result	✓ Passed
Next expiry date	2024-09-01
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #13	2022-08-18 11:22
MOT test number	207154352533
Result	✓ Passed

MOT #12	2022-08-18 09:40
MOT test number	121755777295
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))
Fail	Nearside Headlamp light intensity severely reduced (4.1.4 (a))

MOT #11	2021-09-02 16:42
MOT test number	729102236161
Result	✓ Passed



MOT #10	2020-08-17 07:28
MOT test number	764004332234
Result	✓ Passed
Minor Offside Side repeater flashing more than 120 times a minute (4.4.4 (a))	

MOT #9	2020-08-14 10:16
MOT test number	738500193057
Result	✗ Failed
Fail Nearside Headlamp aim too low (4.1.2 (a))	
Minor Offside Side repeater flashing more than 120 times a minute (4.4.4 (a))	
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Fail Brake fluid contaminated (1.8 (a))	
Fail Offside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))	
Fail Offside Headlamp aim too low (4.1.2 (a))	
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	

MOT #8	2019-08-12 14:50
MOT test number	549098055717
Result	✓ Passed

MOT #7	2018-08-06 15:59
MOT test number	732916122412
Result	✓ Passed

MOT #6	2017-08-31 15:51
MOT test number	103512289852
Result	✓ Passed

**MOT #5** 2017-08-30 10:51**MOT test number** 372711708710**Result** ✗ Failed

Fail Nearside Front Inner Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #4 2016-08-16 15:50**MOT test number** 180290231929**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)

Advice 3rd row seats not in use at time of test

Advice Items removed from driver's view prior to test

MOT #3 2016-08-16 12:19**MOT test number** 172102035748**Result** ✗ Failed

Advice 3rd row seats not in use at time of test

Advice Offside Rear Nail in tyre

Advice Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)

Fail Parking brake: efficiency below requirements (3.7.C.1b)

Advice Items removed from driver's view prior to test

MOT #2 2015-09-01 11:01**MOT test number** 722374289884**Result** ✓ Passed



MOT #1	2015-09-01 11:01
MOT test number	189957829275
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
1 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-01
Last registration	2023-08-14
Complete history	See info



Registration #1	2012-09-01	25 mi
Registration #2	2015-09-01	34.345 mi
Registration #3	2015-09-01	34.345 mi
Registration #4	2016-08-16	48.251 mi
Registration #5	2016-08-16	48.251 mi
Registration #6	2017-08-30	61.083 mi
Registration #7	2017-08-31	61.083 mi
Registration #8	2018-08-06	72.711 mi
Registration #9	2019-08-12	83.460 mi
Registration #10	2020-08-12	94.211 mi
Registration #11	2021-08-12	104.962 mi
Registration #12	2022-08-12	115.713 mi
Registration #13	2023-08-14	126.464 mi
Registration #14	2024-03-28	137.215 mi
Registration #15	2024-03-28	147.966 mi
Registration #16	2024-03-28	158.717 mi
Registration #17	2024-03-28	169.468 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D4HBBU548086
---------------	--------------