





report date: 2024-03-29

#### General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2021-01-31

Pictures 5

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



## MOT history

MOT expiry date	2025-01-31
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	17
Total items failed	2

MOT #13		2024-01-24 15:38
MOT test	number	523118793225
Result		✓ Passed
Next exp	iry date	2025-01-31
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (	(e))
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slight	tly worn (5.1.2 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i	))
Advice	Exhaust has a minor leak of exhaust gases front exhaust joint (6.1.2 (a)	)
<b>Advice</b> rear wish	Offside Front Lower Suspension arm pin or bush worn but not resulting i bone bush (5.3.4 (a) (i))	in excessive movement
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly	worn (5.1.2 (b) (i))
<b>Advice</b> rear wish	Nearside Front Lower Suspension arm pin or bush worn but not resulting bone bush (5.3.4 (a) (i))	g in excessive movement

MOT #12	2023-01-24 10:30
MOT test number	962156508163
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



MOT test number

167280950167

Result

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #10		2021-02-01 11:02
MOT test	number	108267222369
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

Nearside Near Direction indicator slightly discoloured (4.4.5 (a))	
MOT #9	2019-12-23 14:31
MOT test number	314812031919
Result	✓ Passed
MOT #8	2018-12-18 09:41
MOT test number	897012825899
Result	✓ Passed
MOT #7	2017-12-04 12:06
MOT test number	495173804597
Result	✓ Passed
MOT #6	2016-12-19 12:27
MOT test number	600918592350
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



MOT #5 2016-12-07 09:37

**MOT test number** 318723173568

**Result** X Failed

Fail Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**Fail** Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**MOT #4** 2015-12-11 10:47

**MOT test number** 507829478075

**Result** ✓ Passed

MOT #3 2014-12-01 09:31

**MOT test number** 437345534437

Result 

Passed

MOT #2 2013-12-12 10:29

MOT test number 849526743338

**Result** ✓ Passed

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Nearside rear tyre has slight sidewall damage

**Notice** Under-trays fitted obscuring some underside components

**Notice** Both rear tyres deteriorating

**MOT #1** 2012-12-04 15:53

MOT test number 749139632383

CarCheck.co.uk page 5/12





## Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	31 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	UN CONTRACTOR
Current registration	OK OK
Plate since	PD-0-0
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-12-31
Last registration	2024-01-24
Complete history	See info



Registration #1	2009-12-31	20 mi
Registration #2	2012-12-04	31.679 mi
Registration #3	2013-12-12	40.350 mi
Registration #4	2014-12-01	50.024 mi
Registration #5	2015-12-11	62.522 mi
Registration #6	2016-12-07	73.157 mi
Registration #7	2016-12-19	73.497 mi
Registration #8	2017-12-04	82.987 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

**Engine number** 9K79192