



report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER D
Colour	Red
Year of manufacture	-
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-21
Pictures	36
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #12	2021-07-07 13:24
MOT test number	988639748118
Result	✓ Passed
Next expiry date	2022-07-06

MOT #11	2020-11-17 11:35
MOT test number	931004408010
Result	✓ Passed

Advice Front undertray insecure

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #10	2020-11-16 10:25
MOT test number	453261797967
Result	✗ Failed

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Rear Registration plate does not conform to the specified requirements (0.1 (d))

Advice Front undertray insecure

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Front Registration plate does not conform to the specified requirements (0.1 (d))

MOT #9	2019-12-03 16:19
MOT test number	661293150027
Result	✓ Passed

**MOT #8** 2019-02-07 12:06**MOT test number** 557659775549**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge worn (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge worn (5.2.3 (e))**MOT #7** 2018-02-06 16:02**MOT test number** 301175426164**Result** ✓ Passed**MOT #6** 2018-02-06 12:59**MOT test number** 610674539452**Result** ✗ Failed**Fail** Brake fluid warning lamp illuminated (3.6.G.2)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2017-02-07 12:11**MOT test number** 284455172402**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Outer Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear tyre wall perishing**MOT #4** 2015-10-02 13:56**MOT test number** 701676443336**Result** ✓ Passed



MOT #3	2015-02-02 17:05
MOT test number	378373035012
Result	✓ Passed

MOT #2	2015-02-02 14:14
MOT test number	745813035015
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2014-02-13 09:18
MOT test number	756554244020
Result	✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	RV11BXE
Plate since	2019-09-29
Current registration	RV11BXE
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-07
Last registration	2021-07-07
Complete history	See info



Registration #1	2011-03-07	28 mi
Registration #2	2014-02-13	25.270 mi
Registration #3	2015-02-02	31.122 mi
Registration #4	2015-02-02	31.122 mi
Registration #5	2015-10-02	31.683 mi
Registration #6	2017-02-07	42.905 mi
Registration #7	2018-02-06	49.780 mi
Registration #8	2019-05-20	55.277 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70757967