



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Grey
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-03-05
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	24
Total items failed	6

MOT #17	2024-03-04 11:10
MOT test number	528644389539
Result	✓ Passed
Next expiry date	2025-03-05
Advice	Exuste brackets corroded

MOT #16	2024-03-04 11:10
MOT test number	144083916831
Result	✗ Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Exuste brackets corroded

MOT #15	2023-03-06 16:46
MOT test number	496791690771
Result	✓ Passed
Advice	Rear Passenger seat(s) missing at time of test
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear shock absorber outing casing corroded
Advice	Nearside Rear shock absorber outing casing corroded

**MOT #14** 2022-03-01 16:10**MOT test number** 158984281761**Result** ✓ Passed**Advice** Offside Front tyre worn on inner and outer edge**MOT #13** 2022-02-28 09:48**MOT test number** 542520827511**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front tyre worn on inner and outer edge**Fail** Nearside Front Road wheel fixing missing wheel bolt (5.2.1 (a) (i))**MOT #12** 2021-02-06 12:16**MOT test number** 927492466960**Result** ✓ Passed**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge Both sides slightly (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Anti-roll bar linkage ball joint has slight play Both sides (5.3.4 (a) (i))**MOT #11** 2020-03-25 17:17**MOT test number** 280108141777**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10** 2019-04-19 09:18**MOT test number** 519121803761**Result** ✓ Passed**MOT #9** 2018-04-23 11:28**MOT test number** 107175524983**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #8** 2017-04-20 14:33**MOT test number** 627038954574**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2016-04-14 11:18**MOT test number** 292114030479**Result** ✓ Passed**MOT #6** 2015-04-24 11:02**MOT test number** 608114815189**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2015-04-24 08:52**MOT test number** 828764415120**Result** ✗ Failed**Fail** Offside Front Brake pipe twisted (found during steering lock to lock check) (2.2.D.2b)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2014-03-26 13:54**MOT test number** 789685784042**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-03-12 14:27**MOT test number** 327821573064**Result** ✓ Passed**MOT #2** 2012-03-19 10:10**MOT test number** 645189572081**Result** ✓ Passed**MOT #1** 2011-03-29 13:39**MOT test number** 709108381041**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
5 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	5 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-03
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2008-03-03	14 mi
Registration #2	2011-03-29	24.833 mi
Registration #3	2012-03-19	27.641 mi
Registration #4	2013-03-12	30.320 mi
Registration #5	2014-03-26	33.628 mi
Registration #6	2015-04-24	42.832 mi
Registration #7	2015-04-24	42.832 mi
Registration #8	2016-04-14	51.363 mi
Registration #9	2017-04-20	60.147 mi
Registration #10	2018-04-23	67.848 mi
Registration #11	2019-05-20	75.549 mi
Registration #12	2020-06-18	83.250 mi
Registration #13	2021-07-16	90.951 mi
Registration #14	2022-08-14	98.652 mi
Registration #15	2023-09-11	106.353 mi
Registration #16	2024-01-09	114.054 mi
Registration #17	2024-02-06	121.755 mi
Registration #18	2024-03-04	129.456 mi
Registration #19	2024-03-04	137.157 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	560100