



CK57NPU

report date: 2024-03-29

General information

| | |
|---------------------|----------------------|
| Make | FORD |
| Model | FUSION STYLE CLIMATE |
| Colour | Red |
| Year of manufacture | - |
| Top speed | 102 mph |
| 0 - 60 mph | 14.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 79 BHP |
| Max. torque | 124 Nm at 3.500 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.3 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 45.6 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-16 |
| Pictures | 16 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|------------------|
| MOT #17 | 2022-11-12 15:11 |
| MOT test number | 858035215135 |
| Result | ✓ Passed |
| Next expiry date | 2023-11-16 |

| | |
|------------------------|--|
| MOT #16 | 2021-11-15 11:33 |
| MOT test number | 938847100912 |
| Result | ✓ Passed |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |

| | |
|--------------------------------|--|
| MOT #15 | 2021-11-15 11:33 |
| MOT test number | 515987378881 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |

| | |
|------------------------|---|
| MOT #14 | 2020-10-23 10:33 |
| MOT test number | 205896898838 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge measured at 1.9mm (5.2.3 (e)) |

| | |
|------------------------|--|
| MOT #13 | 2019-10-29 15:20 |
| MOT test number | 684798979030 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |

**MOT #12** 2019-10-29 10:54**MOT test number** 669030351795**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-11-06 12:07**MOT test number** 527132892966**Result** ✓ Passed**MOT #10** 2017-11-14 16:09**MOT test number** 347392385020**Result** ✓ Passed**MOT #9** 2017-11-14 10:18**MOT test number** 889460690998**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #8** 2016-11-01 14:17**MOT test number** 164070148221**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-11-17 12:09**MOT test number** 258330981245**Result** ✓ Passed



| | |
|---------------|------------------|
| MOT #6 | 2014-12-09 12:23 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 926863144351 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2013-11-25 11:44 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 265949723342 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2012-11-26 09:27 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 818471332371 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2011-11-28 10:32 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 836332031362 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2010-12-16 11:59 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 860690650301 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #1 | 2010-12-16 11:59 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 842900250316 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✗ Failed |
|---------------|----------|

| | |
|--------------------------------|--|
| Pass with rectification | Offside Stop lamp not working (1.2.1b) |
|--------------------------------|--|



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2007-12-22 |
| Last registration | 2022-11-12 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-12-22 | 26 mi |
| Registration #2 | 2010-12-16 | 10.598 mi |
| Registration #3 | 2011-11-28 | 16.352 mi |
| Registration #4 | 2012-11-26 | 21.605 mi |
| Registration #5 | 2013-11-25 | 26.394 mi |
| Registration #6 | 2014-12-09 | 31.288 mi |
| Registration #7 | 2015-11-17 | 35.942 mi |
| Registration #8 | 2016-11-01 | 43.229 mi |
| Registration #9 | 2017-11-14 | 51.014 mi |
| Registration #10 | 2018-11-28 | 59.802 mi |
| Registration #11 | 2019-11-28 | 68.590 mi |
| Registration #12 | 2020-11-28 | 77.378 mi |
| Registration #13 | 2021-11-28 | 86.166 mi |
| Registration #14 | 2022-11-12 | 94.954 mi |
| Registration #15 | 2023-11-12 | 103.742 mi |
| Registration #16 | 2024-11-12 | 112.530 mi |
| Registration #17 | 2025-11-12 | 121.318 mi |
| Registration #18 | 2026-11-12 | 130.106 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1963 mm |
| Height | 1543 mm |
| Length | 4013 mm |
| Wheel base | 2485 mm |
| Kerb weight | 1199 kg |
| Max. allowed weight | 1605 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 7L05452 |