





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 CRDI CLASSIC
Colour	Black
Year of manufacture	2013
Top speed	99 mph
0 - 60 mph	15.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.500 rpm
Engine capacity	1.120 cc
Cylinders	3
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



Internet history


Entry 2

Date 2021-07-22

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-18

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2022-06-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #8	2021-06-16 14:24
MOT test number	567346220692
Result	✓ Passed
Next expiry date	2022-06-15
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #7	2021-06-16 14:24
MOT test number	182534244238
Result	★ Failed
Pass with rectification all lamps (4.7.1 (b) (ii))	Offside Rear Registration plate lamp inoperative in the case of a single lamp or
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #6	2020-08-15 08:28
MOT test number	801587759107
Result	✓ Passed

CarCheck.co.uk page 3/11



2016-05-10 08:55

MOT #5 2019-09-02 13:50

MOT test number 895265873863

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Under tray fitted

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #4 2018-03-13 15:08

MOT test number 168659328820

Result ✓ Passed

MOT #3 2017-04-25 13:08

MOT test number 507662283025

Advice ADVISE ATTN FRONT O\S AND N\S FRONT TYRES WORN VERY NEAR TO LIMIT -ADVISE VERY EARLY REPLACEMENT

MOT #2 2017-04-25 09:25

MOT test number 211583319845

Result X Failed

Advice ADVISE ATTN FRONT O\S AND N\S FRONT TYRES WORN VERY NEAR TO LIMIT -ADVISE VERY EARLY

REPLACEMENT

Front Front position lamp(s) not working (1.1.A.3b)

Fail

MOT #1

MOT test number 162351470065

Result

Passed

CarCheck.co.uk page 4/11



Tax & MOT check

Tax expired: 1 July 2022



Expired: 15 June 2022 X MOT

Tax status	Expired at 1 July 2022
Days left	669 days too late
MOT expiry date	15 June 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		NDAI

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-04-29
Last registration	2021-06-16
Complete history	See info



Registration #1	2013-04-29	10 mi
Registration #2	2016-05-10	41.121 mi
Registration #3	2017-04-25	56.225 mi
Registration #4	2017-04-25	56.226 mi
Registration #5	2018-03-13	63.609 mi
Registration #6	2019-09-02	68.274 mi
Registration #7		9.77 ss
Registration #8		11.777 ea
Registration #9		9.777 es
Registration #10		11.777 ea
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11




Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1197 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles 2

Engine number D3FADH707201