



report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SPORT
Colour	Red
Year of manufacture	2013
Top speed	131 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.200 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-12
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-03-30
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	14
Total items failed	8

MOT #9	2022-03-31 11:50
--------	------------------

MOT test number	545089541191
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-03-30
------------------	------------

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear handbrake performance is low but working
- Advice** Offside Front Brake pipe corroded, covered in grease or other material rust (1.1.11 (c))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material rust (1.1.11 (c))

**MOT #8** 2022-03-29 08:36**MOT test number** 412228473900**Result** ✗ Failed**Fail** Nearside Rear Service brake lagging in operation (1.2.1 (d))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Brake pipe corroded, covered in grease or other material rust (1.1.11 (c))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Rear handbrake performance is low but working**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material rust (1.1.11 (c))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2021-03-10 10:58**MOT test number** 358553782200**Result** ✓ Passed**MOT #6** 2020-03-16 11:58**MOT test number** 695522985621**Result** ✓ Passed**MOT #5** 2019-03-07 11:25**MOT test number** 380586583501**Result** ✓ Passed

**MOT #4** 2018-03-19 16:50**MOT test number** 856375848282**Result** ✓ Passed**MOT #3** 2018-03-19 13:34**MOT test number** 489113827256**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit 1.8mm (4.1.E.1)**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**MOT #2** 2017-03-17 12:51**MOT test number** 622435346319**Result** ✓ Passed**MOT #1** 2016-02-25 16:15**MOT test number** 161717111709**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
8 September 2022

✕
MOT

Expired:
30 March 2023

Tax status	Expired at 8 September
Days left	598 days too late
MOT expiry date	30 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-03-05
Last registration	2022-03-31
Complete history	See info



Registration #1	2013-03-05	13 mi
Registration #2	2016-02-25	42.354 mi
Registration #3	2017-03-17	53.499 mi
Registration #4	2018-03-19	70.128 mi
Registration #5	2018-03-19	70.128 mi
Registration #6	2019-03-07	84.074 mi
Registration #7	2019-03-07	84.074 mi
Registration #8	2019-03-07	84.074 mi
Registration #9	2019-03-07	84.074 mi
Registration #10	2019-03-07	84.074 mi
Registration #11	2019-03-07	84.074 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2830 mm
Kerb weight	1405 kg
Max. allowed weight	2055 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	SH 30264314