



report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC CLI. P
Colour	Silver
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	157 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-09-13
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	19
Total items failed	5

MOT #19	2023-08-16 13:44
MOT test number	155994271658
Result	✓ Passed
Next expiry date	2024-09-13
Advice	Offside Oil leak, but not excessive Gearbox (8.4.1 (a) (i))

MOT #18	2022-09-14 12:32
MOT test number	309587037145
Result	✓ Passed

**MOT #17**

2021-12-18 12:02

MOT test number

315167609996

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #16

2020-12-15 12:15

MOT test number

591003617646

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #15	2020-01-10 09:30
MOT test number	162141827369
Result	✓ Passed
MOT #14	2019-01-07 16:36
MOT test number	280767065986
Result	✓ Passed
MOT #13	2018-01-09 16:16
MOT test number	977808367157
Result	✓ Passed
MOT #12	2018-01-09 10:27
MOT test number	425974493096
Result	✗ Failed
<div>Fail Offside Front coil spring broken (2.4.C.1a)</div>	
MOT #11	2017-01-16 17:49
MOT test number	433421256839
Result	✓ Passed
MOT #10	2016-01-07 14:43
MOT test number	575077812570
Result	✓ Passed
MOT #9	2015-01-07 10:38
MOT test number	539267505060
Result	✓ Passed



MOT #8	2015-01-07 10:38
MOT test number	206397505034
Result	✗ Failed
Pass with rectification	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
Pass with rectification	Stop lamp not working (1.2.1b)
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
MOT #7	2014-01-21 09:27
MOT test number	648571624085
Result	✓ Passed
MOT #6	2013-01-28 15:28
MOT test number	629078423087
Result	✓ Passed
MOT #5	2012-12-12 16:11
MOT test number	129307442374
Result	✓ Passed
MOT #4	2011-10-17 10:35
MOT test number	347240691459
Result	✓ Passed
MOT #3	2010-09-21 12:12
MOT test number	624424160212
Result	✓ Passed
MOT #2	2009-09-25 15:02
MOT test number	312558069218
Result	✓ Passed



MOT #1	2009-09-24 09:24
MOT test number	930737869259
Result	✗ Failed
<div><div>Fail</div>Offside Front coil spring incomplete (2.4.C.1a)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
13 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RO56XCP
Plate since	2024-03-29
Current registration	RO56XCP
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-30
Last registration	2023-08-16
Complete history	See info



Registration #1	2006-09-30	10 mi
Registration #2	2009-09-24	12.825 mi
Registration #3	2009-09-25	12.825 mi
Registration #4	2010-09-21	14.231 mi
Registration #5	2011-10-17	17.101 mi
Registration #6	2012-12-12	17.253 mi
Registration #7	2013-01-28	17.278 mi
Registration #8	2014-01-21	21.898 mi
Registration #9	2015-01-07	26.334 mi
Registration #10	2016-01-07	29.442 mi
Registration #11	2016-01-07	29.442 mi
Registration #12	2016-01-07	29.442 mi
Registration #13	2016-01-07	29.442 mi
Registration #14	2016-01-07	29.442 mi
Registration #15	2016-01-07	29.442 mi
Registration #16	2016-01-07	29.442 mi
Registration #17	2016-01-07	29.442 mi
Registration #18	2016-01-07	29.442 mi
Registration #19	2016-01-07	29.442 mi
Registration #20	2016-01-07	29.442 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1447 mm
Length	4342 mm
Wheel base	2640 mm
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

6B85018