





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Silver
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Engine capacity	2.496 сс
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	37.2 mpg
Consumption combined	27.4 mpg
CO2 emission	244 g/km
CO2 label	L



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-30

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-10
D' I I I I I I I I I I I I I I I I I I I	20

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history


MOT expiry date	2024-08-15
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	31
Total items failed	9

MOT #18		2023-08-16 13:13
MOT test	number	549072805619
Result		✓ Passed
Next expi	ry date	2024-08-15
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Items removed from driver's view prior to test	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



report date: 2024-03-28



MOT #16		2022-07-26 09:02
MOT test	number	609145454967
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #15 2022-07-26 09:02 976374993728 **MOT** test number Result × Failed **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT test number

Result

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front wipers deteriorating

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13	2020-09-23 09:05
MOT test number	997911164269
Result	✓ Passed

MO1 #12	2018-11-27 15:34
MOT test number	259920165328
Result	✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #11 2017-11-28 08:42

MOT test number 223074919379

Result \(\sqrt{Passed} \)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

MOT #10 2017-11-27 13:27

MOT test number 709320507030

Result X Failed

Fail Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #9 2016-11-25 14:44

MOT test number 624771023226

Result
✓ Passed

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice O/s/r tyre inner wall cracking

MOT #8 2015-06-17 08:35

MOT test number 218448065116

MOT #7 2015-04-24 10:33

MOT test number 158224315100

Result

Passed

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #6		2014-04-25 15:56
MOT test	number	258035214426
Result		✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	

MOT #5	2013-07-22 11:41
MOT test number	156563303286
Result	✓ Passed
MOT #4	2012-08-07 17:05
MOT test number	359140622428
Result	✓ Passed
MOT #3	2012-08-07 15:35
MOT test number	145810022250
Result	X Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice Slight sidewalldamage n/s/f	

MOT #2		2011-08-12 09:53
MOT test	number	139054821269
Result		✓ Passed
Notice	Small stone chips to front screen	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #1 2010-09-13 11:38

MOT test number 931876850243

CarCheck.co.uk page 8/15



BN57FYB report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 9/15




report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

e when miscery	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of states	
Current registration	OK SIE
Plate since	
Current registration	UK CONTRACTOR
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-24
Last registration	2023-08-16
Complete history	See info



Registration #1	2007-09-24	28 mi
Registration #2	2010-09-13	8.567 mi
Registration #3	2011-08-12	11.470 mi
Registration #4	2012-08-07	14.096 mi
Registration #5	2012-08-07	14.096 mi
Registration #6	2013-07-22	17.202 mi
Registration #7	2014-04-25	19.542 mi
Registration #8	2015-04-24	20.895 mi
Registration #9	2015-06-17	20.901 mi
Registration #10	2016-11-25	30.476 mi
Registration #11	2017-11-27	34.949 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 mi

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1595 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	548873414XB

CarCheck.co.uk page 15/15