



HYUNDAI

BT64KDO


report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	Blue
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-20
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-14
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	8
Total items failed	14

MOT #11	2023-11-15 14:46
MOT test number	947213474180
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Both front tyres bald on inner edge
Advice	Bonnet strut faulty

MOT #10	2023-11-01 10:49
MOT test number	335949213278
Result	✗ Failed
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Emissions unable to be completed NO COOLANT... (8.2.2.2 (e))
Fail	Offside Headlamp aim too low (4.1.2 (a))
Advice	Both front tyres bald on inner edge
Fail	Nearside Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))
Fail	Nearside Headlamp aim too low (4.1.2 (a))
Advice	Bonnet strut faulty

**MOT #9** 2022-11-03 16:54**MOT test number** 511730481017**Result** ✓ Passed**MOT #8** 2022-11-02 14:51**MOT test number** 696257415001**Result** ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

MOT #7 2021-11-02 16:37**MOT test number** 531407342847**Result** ✓ Passed**MOT #6** 2021-02-01 11:30**MOT test number** 521812055573**Result** ✓ Passed**MOT #5** 2020-01-16 13:28**MOT test number** 771776545294**Result** ✓ Passed

- Minor** Nearside Side repeater lens defective which has no effect on emitted light cracked (4.4.1 (b) (i))

**MOT #4** 2020-01-16 08:49**MOT test number** 353313619428**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Nearside Side repeater lens defective which has no effect on emitted light cracked (4.4.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-01-08 09:46**MOT test number** 105527650881**Result** ✓ Passed**MOT #2** 2018-01-03 16:25**MOT test number** 440548463927**Result** ✓ Passed**MOT #1** 2018-01-03 13:34**MOT test number** 995534467165**Result** ✗ Failed**Fail** Nearside Front wheel bearing has excessive play (2.5.A.3c)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-01-19
Last registration	2023-11-15
Complete history	See info



Registration #1	2015-01-19	14 mi
Registration #2	2018-01-03	10.858 mi
Registration #3	2018-01-03	10.859 mi
Registration #4	2019-01-08	18.745 mi
Registration #5	2020-01-16	29.995 mi
Registration #6	2020-01-16	29.995 mi
Registration #7	2021-02-01	35.045 mi
Registration #8	2023-11-15	35.045 mi
Registration #9	2023-11-15	35.045 mi
Registration #10	2023-11-15	35.045 mi
Registration #11	2023-11-15	35.045 mi
Registration #12	2023-11-15	35.045 mi
Registration #13	2023-11-15	35.045 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4FDEU485853