





report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EASY
Colour	White
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/13



FM14UFC report date: 2024-03-29

Internet history

E	n	t	r۱	,	3
_		•		,	_

Date	2021-10-23
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 2

Date	2021-10-23
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

Date	2021-10-23
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2025-02-06
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	20
Total items failed	12

MOT #10	2024-01-22 11:01
MOT test number	294526261669
Result	✓ Passed
Next expiry date	2025-02-06
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear exhaust corroded	

MOT #9	2023-01-23 10:06
MOT test number	870449420279
Result	✓ Passed
MOT #8	2022-02-07 15:11
MOT test number	610321774234
Result	✓ Passed
Advice Rear exhuast corroded	

CarCheck.co.uk page 3/13



Result

FM14UFC

report date: 2024-03-29

× Failed

MOT #7 2022-02-04 14:09

MOT test number 763955821547

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Rear exhuast corroded

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #6 2020-10-07 09:59

MOT test number 178545684691

Advice Exhaust corroded

Advice Tyre walls perishing

MOT #5 2019-04-11 12:15

MOT test number 161083582736

Result ✓ Passed


Advice No.plate cracked

Advice Front tyre perishing

CarCheck.co.uk page 4/13



report date: 2024-03-29



MOT #3		2018-04-30 15:57
MOT test	number	189454206373
Result		✓ Passed
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Brake effort low	
Advice	Items removed from driver's view prior to test	
Advice	Exhaust rusty	
Advice	Nearside sill damaged	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2 2018-04-26 14:37

MOT test number 205466792896

Result

× Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice

Nearside sill damaged

Fail

Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Brake effort low

Advice

Items removed from driver's view prior to test

Fail

Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)

Advice

Exhaust rusty

MOT #1 2017-05-05 10:03

MOT test number 143040809333

CarCheck.co.uk page 6/13



FM14UFC report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	6 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



FM14UFC report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

FM14UFC

report date: 2024-03-29

More info >

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FIAT had different number plates.

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-07-30
Last registration	2024-01-22
Complete history	See info



Registration #1	2014-07-30	8 mi
Registration #2	2017-05-05	17.903 mi
Registration #3	2018-04-26	23.175 mi
Registration #4	2018-04-30	23.177 mi
Registration #5	2019-04-10	27.936 mi
Registration #6	2019-04-11	27.937 mi
Registration #7	2020-10-07	32.196 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11,177 esi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles2Engine number0798077