



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	MODUS DYNAMIQUE 16V
Colour	Blue
Year of manufacture	2005
Top speed	114 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-05-22
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-17
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	27
Total items failed	10

MOT #20	2023-07-06 11:18
MOT test number	638033996739
Result	✓ Passed
Next expiry date	2024-07-17

MOT #19	2023-07-05 12:48
MOT test number	874366258094
Result	✗ Failed
Fail	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #18	2022-07-14 07:51
MOT test number	754519019506
Result	✓ Passed
Advice	Oil leak, but not excessive gear box (8.4.1 (a) (i))
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2022-07-07 08:41

MOT test number

992186076356

Result**✗ Failed****Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Oil leaking excessively from transmission and engine (8.4.1 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #16**

2021-07-03 09:21

MOT test number

326543079829

Result**✓ Passed****Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output N/S & O/S (4.1.4 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin N/S & O/S (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Hand Brake Has Little Reserve Travel

**MOT #15** 2020-07-07 08:27**MOT test number** 852323307254**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear park brake low**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #14** 2019-07-11 08:39**MOT test number** 373685849612**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #13** 2018-07-16 11:14**MOT test number** 534775009585**Result** ✓ Passed**MOT #12** 2017-07-11 14:18**MOT test number** 170614914807**Result** ✓ Passed**MOT #11** 2017-07-11 13:41**MOT test number** 491898084287**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #10** 2016-07-18 13:49**MOT test number** 750302885019**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #9** 2016-07-18 13:49**MOT test number** 544169028317**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #8** 2015-03-04 14:17**MOT test number** 136863965018**Result** ✓ Passed**MOT #7** 2015-03-04 09:00**MOT test number** 519603565013**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Notice** Nail in nearside rear tyre**MOT #6** 2014-03-25 10:51**MOT test number** 849234484071**Result** ✓ Passed

**MOT #5** 2012-11-12 16:03**MOT test number** 938757112346**Result** ✓ Passed**Notice** Offside rear brake binding slightly and pads slightly low**MOT #4** 2011-05-04 14:14**MOT test number** 307804721185**Result** ✓ Passed**Notice** N/s front tyre wall has slight cut but not showing cords**MOT #3** 2010-05-11 15:33**MOT test number** 230271130115**Result** ✓ Passed**MOT #2** 2009-05-26 14:08**MOT test number** 464956249151**Result** ✓ Passed**MOT #1** 2008-05-07 13:21**MOT test number** 773248228160**Result** ✓ Passed**Notice** Nail in nearside rear tyre



Tax & MOT check

X

Untaxed

Tax expired:
10 April 2024

✓

MOT

Expires:
17 July 2024

Tax status	Expired at 10 April 2024
Days left	19 days too late
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-06-03
Last registration	2023-07-06
Complete history	See info



Registration #1	2005-06-03	10 mi
Registration #2	2008-05-07	10.362 mi
Registration #3	2009-05-26	13.703 mi
Registration #4	2010-05-11	19.219 mi
Registration #5	2011-05-04	25.989 mi
Registration #6	2012-11-12	35.176 mi
Registration #7	2014-03-25	40.293 mi
Registration #8	2015-03-04	47.319 mi
Registration #9	2015-03-04	47.319 mi
Registration #10	2016-07-18	56.206 mi
Registration #11	2016-07-18	56.206 mi
Registration #12	2016-07-18	56.206 mi
Registration #13	2016-07-18	56.206 mi
Registration #14	2016-07-18	56.206 mi
Registration #15	2016-07-18	56.206 mi
Registration #16	2016-07-18	56.206 mi
Registration #17	2016-07-18	56.206 mi
Registration #18	2016-07-18	56.206 mi
Registration #19	2016-07-18	56.206 mi
Registration #20	2016-07-18	56.206 mi
Registration #21	2016-07-18	56.206 mi
Registration #22	2016-07-18	56.206 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1960 mm
Height	1589 mm
Length	3792 mm
Wheel base	2482 mm
Kerb weight	1205 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D006888