



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD CTDI EX
Colour	Brown
Year of manufacture	-
Top speed	132 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	140 Nm at 4.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history


Entry 2

Date	2022-12-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

Entry 1

Date	2021-11-06
Pictures	30
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #19	2022-01-25 11:56
MOT test number	458362924096
Result	✓ Passed
Next expiry date	2023-01-24

MOT #18	2022-01-21 16:51
MOT test number	325580905511
Result	✗ Failed

Fail Nearside Steering locking device missing split pin missing track rod end (2.1.3 (d))

Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #17	2021-01-18 14:49
MOT test number	729691647591
Result	✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16	2020-01-22 10:40
MOT test number	300108254605
Result	✓ Passed

MOT #15	2019-01-14 15:51
MOT test number	328783532179
Result	✓ Passed

**MOT #14** 2018-01-17 16:44**MOT test number** 437051420736**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #13** 2017-01-19 17:14**MOT test number** 112281982761**Result** ✓ Passed**MOT #12** 2016-01-05 13:55**MOT test number** 658180144320**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #11** 2015-01-23 15:00**MOT test number** 727213925006**Result** ✓ Passed**Advice** Power steering ram(s) has slight seepage from a component (2.3.3b)

**MOT #10** 2015-01-22 10:00**MOT test number** 409122225081**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Power steering ram(s) has slight seepage from a component (2.3.3b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-01-24 12:34**MOT test number** 307284124036**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components

**MOT #8** 2014-01-22 10:18**MOT test number** 125032124051**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Battery leaking electrolyte (1.9.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside rear inner position lamp not working**MOT #7** 2013-01-11 16:03**MOT test number** 118411613422**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2013-01-11 16:03**MOT test number** 979381613049**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #5** 2012-01-09 10:42**MOT test number** 408679102081**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-01-09 10:42**MOT test number** 126789702455**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-01-11 12:13**MOT test number** 365941511096**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-08-31 15:55**MOT test number** 610133140281**Result** ✓ Passed**MOT #1** 2009-08-18 12:45**MOT test number** 291790339298**Result** ✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	LD56KNH
Plate since	2019-03-28
Current registration	LD56KNH
Plate since	2019-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-07
Last registration	2022-01-25
Complete history	See info




Registration #1	2006-09-07	12 mi
Registration #2	2009-08-18	42.043 mi
Registration #3	2010-08-31	52.872 mi
Registration #4	2011-01-11	54.983 mi
Registration #5	2012-01-09	69.636 mi
Registration #6	2013-01-11	76.748 mi
Registration #7	2014-01-22	95.237 mi
Registration #8	2014-01-24	95.237 mi
Registration #9	2015-01-22	113.342 mi
Registration #10	2015-01-23	113.342 mi
Registration #11	2015-01-23	113.342 mi
Registration #12	2015-01-23	113.342 mi
Registration #13	2015-01-23	113.342 mi
Registration #14	2015-01-23	113.342 mi
Registration #15	2015-01-23	113.342 mi
Registration #16	2015-01-23	113.342 mi
Registration #17	2015-01-23	113.342 mi
Registration #18	2015-01-23	113.342 mi
Registration #19	2015-01-23	113.342 mi
Registration #20	2015-01-23	113.342 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1477 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22A13004809