



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V CTDI SPORT
Colour	Silver
Year of manufacture	2006
Top speed	103 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H









Internet history

Entry 1

Date	2021-09-19
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-06
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	19
Total items failed	7

MOT #17 2023-06-15 09:55**MOT test number** 104460446654**Result** Passed**Next expiry date** 2024-07-06

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16 2022-06-28 09:30**MOT test number** 441002354308**Result** Passed**MOT #15** 2022-06-28 09:30**MOT test number** 878225070940**Result** Failed

- Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #14** 2021-07-07 15:41**MOT test number** 513466583410**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Sub-frame corroded but not seriously weakened axle (5.3.3 (b) (i))**Advice** Exhaust system corroded**MOT #13** 2020-08-29 09:45**MOT test number** 103626493909**Result** ✓ Passed**Advice** Central Front Exhaust corroded**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** All prescribed area slightly corroded**MOT #12** 2019-06-13 10:46**MOT test number** 602963189617**Result** ✓ Passed**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2018-06-16 10:18**MOT test number** 609679831443**Result** ✓ Passed

**MOT #10** 2017-05-24 13:46**MOT test number** 592920216796**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin offside (3.5.1g)**MOT #9** 2016-06-07 14:36**MOT test number** 290255297858**Result** ✓ Passed**Advice** Outer wall split on nearside front tyre**MOT #8** 2016-06-07 11:05**MOT test number** 302785725539**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Outer wall split on nearside front tyre**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #7** 2015-06-17 11:06**MOT test number** 965118465115**Result** ✓ Passed**MOT #6** 2014-10-08 09:27**MOT test number** 628621184233**Result** ✓ Passed



MOT #5	2013-10-02 12:26
MOT test number	707355673249
Result	✓ Passed
MOT #4	2012-10-03 10:35
MOT test number	216477572298
Result	✓ Passed
MOT #3	2011-10-05 11:45
MOT test number	866538671200
Result	✓ Passed
MOT #2	2010-10-12 14:44
MOT test number	691505680271
Result	✓ Passed
MOT #1	2009-09-21 11:57
MOT test number	670604469237
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-28
Last registration	2023-06-15
Complete history	See info



Registration #1	2006-09-28	26 mi
Registration #2	2009-09-21	27.404 mi
Registration #3	2010-10-12	41.807 mi
Registration #4	2011-10-05	53.741 mi
Registration #5	2012-10-03	62.163 mi
Registration #6	2013-10-02	70.475 mi
Registration #7	2014-10-08	77.121 mi
Registration #8	2015-06-17	77.434 mi
Registration #9	2016-06-07	83.044 mi
Registration #10	2016-06-07	83.044 mi
Registration #11	2016-06-07	83.044 mi
Registration #12	2016-06-07	83.044 mi
Registration #13	2016-06-07	83.044 mi
Registration #14	2016-06-07	83.044 mi
Registration #15	2016-06-07	83.044 mi
Registration #16	2016-06-07	83.044 mi
Registration #17	2016-06-07	83.044 mi
Registration #18	2016-06-07	83.044 mi
Registration #19	2016-06-07	83.044 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1584 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	N22A11503858