



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 CLASSIC
Colour	White
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	C





## MOT history

MOT expiry date	2025-04-07
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	26
Total items failed	3

MOT #11 2024-04-08 09:39

MOT test number 671413931458

Result ✓ Passed

Next expiry date 2025-04-07

- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10 2024-04-08 09:39

MOT test number 596610419418

Result ✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9**

2023-05-11 14:37

**MOT test number**

934411567811

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #8**

2022-05-17 13:37

**MOT test number**

605178741106

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to axle flexy (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to caliper flexy (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to axle flexy (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to caliper flexy (1.1.11 (c))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #7**

2021-05-20 11:11

**MOT test number**

714510301071

**Result**

✓ Passed

**MOT #6** 2020-04-30 15:40**MOT test number** 571812509909**Result** ✓ Passed**MOT #5** 2019-01-08 15:03**MOT test number** 169644624312**Result** ✓ Passed**MOT #4** 2018-01-03 11:52**MOT test number** 458890979030**Result** ✓ Passed**Advice** Nearside Rear seatbelt slow to retract.**MOT #3** 2018-01-03 11:03**MOT test number** 378042694904**Result** ✗ Failed**Fail** Spare wheel insecure (6.4.2)**Advice** Nearside Rear seatbelt slow to retract.**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2017-01-06 11:38**MOT test number** 355391298210**Result** ✓ Passed**MOT #1** 2016-01-06 14:59**MOT test number** 548517493455**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
7 April 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	7 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-01-16
Last registration	2024-04-08
Complete history	<a href="#">See info</a>



Registration #1	2013-01-16	15 mi
Registration #2	2016-01-06	28.686 mi
Registration #3	2017-01-06	34.368 mi
Registration #4	2018-01-03	35.649 mi
Registration #5	2018-01-03	35.649 mi
Registration #6	2019-01-08	38.180 mi
Registration #7	2019-01-08	38.180 mi
Registration #8	2019-01-08	38.180 mi
Registration #9	2019-01-08	38.180 mi
Registration #10	2019-01-08	38.180 mi
Registration #11	2019-01-08	38.180 mi
Registration #12	2019-01-08	38.180 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1073 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4LACM960237